



**US Army Corps
of Engineers**
Louisville District

SUPERFUND FIVE YEAR REVIEW REPORT

LEE'S LANE LANDFILL

LOUISVILLE, JEFFERSON COUNTY, KY

EPA ID: KYD980557052

**PREPARED FOR
U.S. ENVIRONMENTAL PROTECTION AGENCY
REGION IV**

JUNE 2003

SUPERFUND FIVE-YEAR REVIEW REPORT

Lee's Lane Landfill

Louisville, Jefferson County, KY

EPA OD: KYD980557052

**PREPARED FOR
THE U.S. ENVIRONMENTAL PROTECTION AGENCY, REGION IV
ATLANTA, GA**

**PREPARED BY:
US Army Corps of Engineers
Louisville District
CELRL-ED-E**

June 2003

Five-Year Review Report

Table of Contents

List of Acronyms

Executive Summary

Five-Year Review Summary Form

I. Introduction	1
II. Site Chronology	3
III. Background	4
Physical Characteristics	4
Land and Resource Use	5
History of Contamination	5
Initial Response	6
Basis for Taking Action	6
IV. Remedial Actions	8
Enforcement Decision Document	8
Remedy Implementation	8
System Operations/Operation and Maintenance (O&M)	8
V. Progress Since the Last Five-Year Review	9
VI. Five-Year Review Process	10
Administrative Components	10
Document Review	10
ARARs Review	14
Data Review	14
Site Inspection Findings	17
Site Inspection Summary	18
Additional Inquiry	18
Community Involvement Activities	18

VII. Technical Assessment

Question A: Is the remedy functioning as intended by the decision documents?	19
Question B: Are the exposure assumptions, toxicity data, cleanup levels, and remedial action objectives (RAOs) used at the time of the remedy selection still valid?	19
Question C: Has any other information come to light that could call into question the protectiveness of the remedy?	20
Technical Assessment Summary	21

VIII. Issues	21
---------------------------	----

IX. Recommendations and Follow-up Actions	21
--	----

X. Protectiveness Statement(s)	22
---	----

XI. Next Review	23
------------------------------	----

Tables

Table 1	Chronology of Site Events
Table 2	Comparison of Previous ACLS to New Standards
Table 3	Issues
Table 4	Recommendations and Follow-up Actions

Attachments

A Figures

Figure 1	Site Map
Figure 2	Site Layout
Figure 3	Monitoring Locations
Figure 4	Site Inspection Map
Figure 5	Subsurface Gas Collection System
Figure 6	Cross-Section of Landfill
Figure 7	1998 Aerial Photograph of Site
Figure 8	1961 Topographic Map of Site
Figure 9 (A-E)	Descriptions of Landfill Sections

B Photographs

Photograph 1	Entrance Gate at Lee's Lane
Photograph 2	View Looking North Along the Levee from the Lee's Lane Crossing
Photograph 3	Top of Gas Collection Well #28 Under Water Pounded in the Ditch Parallel to the Line of Gas Collection Wells

Photograph 4	Blower House and Gas Collection Wells from Lee's Lane
Photograph 5A,B	View Looking South Along the Levee from the Lee's Lane Crossing
Photograph 6	Approach to Landfill Along Lee's Lane
Photograph 7	Central Tract Wooded, Hummocky Area
Photograph 8	Rock-Lined Ditch at North End of Central Tract and Wooded Northern Tract
Photograph 9	Rip-Rap Bank Protection
Photograph 10	Settlement Monuments
Photograph 11	Ruts Along Capped Area
Photograph 12	Blocked Shale-Lined Drainage Ditch Across Capped Area at the Top of the Rip-Rapped Slope
Photograph 13A,B	Ponded Water Upstream of Drainage Pipe Blockage
Photograph 14	Access Road in Southern Tract
Photograph 15A,B	Debris and Hummocky Surface in Southern Tract
Photograph 16	Ruts and Eroded Surface Due to Quad-Runner ATV Traffic; View from Putnam Road Looking South
Photograph 17	Piping at the Subsurface Gas Collection Blower House
Photograph 18	Barrier Across Putnam Road
Photograph 19A,B	Water Meter and Fire Hydrant Along Putnam Road
Photograph 20A,B	Elastic Material Observed at Surface Within the Landfill
Photograph 21	Buried Drum with Elastic Material

C Forms

- 1 5-Year Review Site Inspection Attendees
- 2 5-Year Review Site Inspection Checklist (from MSD)
- 3 Groundwater Monitoring Data
- 4 Gas Monitoring Well Data
- 5 Ambient Air Monitoring
- 6 Plot of Methane Measurements in Gas Monitoring Wells
- 7 Plot of Methane Measurements in Ambient Air
- 8 Telephone Interviews
- 9 Correspondence with SCS Engineers

List of Acronyms

ACL	Alternate Concentration Limit
ARAR	Applicable or Relevant and Appropriate Requirement
ATSDR	Agency for Toxic Substances and Disease Registry
ATV	All-Terrain Vehicle
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
CFS	Cubic feet per second
EDD	Enforcement Decision Document
EPA	United States Environmental Protection Agency
CFR	Code of Federal Regulations
HRS	Hazard Ranking System
HTRW	Hazardous, Toxic, Radiological Waste
KNREPC	Kentucky Natural Resources and Environmental Protection Cabinet
LEL	Lower Explosive Limit
MCL	Maximum Contaminant Level
MSD	Metropolitan Sewer District
NCP	National Contingency Plan
NPL	National Priorities List
O&M	Operation and Maintenance
RA	Remedial Action
RAO	Remedial Action Objective
RD	Remedial Design
RI/FS	Remedial Investigation/Feasibility Study
ROD	Record of Decision
SAD	Surveillance and Analysis Division of the Kentucky Division of Waste Management
SDWA	Safe Drinking Water Act
SMCL	Secondary Maximum Contaminant Level
UST	Underground Storage Tank

Executive Summary

The remedy for the Lee's Lane Landfill in Louisville, KY included operation and maintenance of a subsurface gas collection system, provision for alternate water supplies, removal of exposed drums, capping soils in hot spot areas, imposition of site security measures, and monitoring of groundwater, gas, and air. The site achieved construction completion on March 18, 1988. Operation and maintenance activities at the site were transferred to the Louisville Metropolitan Sewer District (MSD) in 1991. The trigger for this third five-year review was the completion of the second five-year report, dated June 30, 1998.

The assessment conducted for this five-year review found that the remedy was constructed and has been operated and maintained in accordance with the requirements of the Enforcement Decision Document (EDD). The remedy has functioned as designed.

The remedy at the Lee's Lane Landfill currently protects human health and the environment, because it significantly reduces the migration of explosive gases from the landfill and minimizes on-site and off-site exposure to contamination. To insure that the remedy will be protective in the long-term, a complete re-evaluation of the subsurface gas collection system is needed. Although many practical site security measures have been taken, the limits and liabilities of current measures need to be re-evaluated in terms of pedestrian traffic resulting from the recently constructed walking path adjacent to the landfill and uncontrolled trespasser quad-runner ATV traffic within the landfill itself.

The main recommendation in this report is that the principal component of the remediation, operation of the subsurface gas collection system, be evaluated immediately to ensure continued effectiveness. The system should be overhauled if necessary and monitored. Results of the evaluation and monitoring should be reported in the next five-year review which will be due by June 30, 2008.

Five-Year Review Summary Form

SITE IDENTIFICATION		
Site name (from WasteLAN): Lee's Lane Landfill		
EPA ID (from WasteLAN): KYD980557052		
Region: 04	State: KY	City/County: Louisville / Jefferson
SITE STATUS		
NPL status: Deleted 04/25/96		
Remediation status : Complete		
Multiple OUs? NO	Construction completion date: 03/18/1988	
Has site been put into reuse? NO		
REVIEW STATUS		
Lead agency: US EPA, Region 4		
Author name: John Jent		
Author title: Project Engineer	Author affiliation: US Corps of Engineers	
Review period:** 12 /15 /2002 to 03 /30 /2003		
Date(s) of site inspection: 02/ 25/2003		
Type of review: Statutory		
Review number: 3		
Triggering action: Previous Five-Year Review Report Date		
Triggering action date (from WasteLAN): 06 / 30 / 1998		
Due date (five years after triggering action date): 06 / 30 / 2003		

* ["OU" refers to operable unit.]

** [Review period should correspond to the actual start and end dates of the Five-Year Review in WasteLAN.]

Five-Year Review Summary Form, cont'd

Issues:

Increasing concentrations of methane gas levels, in both the gas monitoring wells and ambient air sampling, indicate a very strong need for an extensive evaluation of the subsurface gas collection system. As part of this review, conditions at the site were discussed with Mr. James J. Walsh of SCS Engineers. SCS Engineers initially designed the subsurface gas collection system and later repaired it. Based on the discussion, it was the recommendation of SCS Engineers that the subsurface gas collection system be thoroughly evaluated as soon as possible.

Although MSD has taken many feasible measures to provide site security, the placement of pedestrian path along the levee top and the large amount of uncontrolled trespasser quad-runner ATV traffic require that MSD, the City of Louisville, and the EPA further consider the limits and ramifications of site security measures.

MSD operation and maintenance have been hampered by not having at its disposal the basic project documentation. Additionally, such information should have been available at a nearby public repository.

Since all residents adjacent to the project are now connected to a municipal water supply, there is no need to continue monitoring Groundwater Wells MWs-A, B, and 02 since there is no longer a complete pathway for groundwater exposure.

New Kentucky Water Quality Standards require additional laboratory analyses for the groundwater samples from Groundwater MWs-04,05.


Recommendations and Follow-up Actions:

- 1 Maintain already programmed (O&M) activities by the MSD and increase the level of oversight by the Kentucky Natural Resources and Environmental Protection Cabinet.
- 2 Obtain basic documentation, design, and O&M information for the subsurface gas collection system from the firm that designed it.
- 3 Conduct a comprehensive evaluation of the subsurface gas collection system using a qualified firm.
- 4 Re-evaluate site security measures, limits, and liabilities in view of pedestrian and uncontrolled trespasser quad-runner ATV traffic.

- 5 Improve site drainage to minimize ponding of surface water.
- 6 Insure more timely evaluation of the results of site monitoring information to recognize significant trends and to determine if measured parameters exceed regulatory limits.
- 7 Re-establish a repository for project related information, especially operations and maintenance manuals and as-built drawings.
- 8 Develop a plan coordinated with the MSD, the City of Louisville, and the EPA that addresses the current issues.
- 9 Present to the public the plan developed to resolve the current issues.
- 10 Discontinue monitoring of groundwater wells, MWS-A,B,02.
- 11 Add laboratory analyses for beryllium, hexavalent chromium(discontinue total chromium),copper and filtered lead for samples from groundwater monitoring wells, MW-04 and 05.

Protectiveness Statement:

The remedy at the Lee's Lane Landfill currently protects human health and the environment, because it significantly reduces the migration of explosive gases from the landfill and minimizes on-site and off-site exposure to contamination. In order to insure that the subsurface gas collection system continues to function at its current level or better, a re-evaluation of the system will be initiated by December 2003. Although many practical site security measures have been taken, the limits and liabilities of current measures need to be re-evaluated in terms of pedestrian traffic resulting from the recently constructed walking path adjacent to the landfill and uncontrolled trespasser quad-runner ATV traffic within the landfill itself.


Winston A. Smith, Director
Waste Management Division
US EPA, Region 4

7-2-07
Date

Five-Year Review Report

1. Introduction

The Purpose of the Review

The purpose of five-year reviews is to determine whether the remedy at a site is protective of human health and the environment. The methods, findings, and conclusions of reviews are documented in Five-Year Review reports. In addition, Five-Year Review reports identify issues found during the review, and make recommendations to address them.

Authority for Conducting the Five-Year Review

The Agency is preparing this five-year review pursuant to CERCLA §121 and the National Contingency Plan (NCP). CERCLA §121 states:

If the President selects a remedial action that results in any hazardous substances, pollutants, or contaminants remaining at the site, the President shall review such remedial action no less often than each five years after the initiation of such remedial action to assure that human health and the environment are being protected by the remedial action being implemented. In addition, if upon such review it is the judgment of the President that action is appropriate at such site in accordance with section [104] or [106], the President shall take or require such action. The President shall report to the Congress a list of facilities for which such review is required, the results of all such reviews, and any actions taken as a result of such reviews.

The agency interpreted this requirement further in the National Contingency Plan (NCP); 40 CFR §300.430(f)(4)(ii) states:

If a remedial action is selected that results in hazardous substances, pollutants, or contaminants remaining at the site above levels that allow for unlimited use and unrestricted exposure, the lead agency shall review such action no less often than every five years after the initiation of the selected remedial action.

Who Conducted the Five-Year Review

Personnel of the U.S. Army Corps of Engineers, John Jent, Nathaniel Peters, and Al Scalzo of the Louisville District, conducted this five-year review of the remedial actions implemented at the Lee's Lane Landfill in Louisville, KY. The review was conducted from December 2002 through March 2003. This report documents the results of the review. Support of the US Army Corps of Engineers for this review was provided for under EPA Work Authorization Form of Interagency Agreement (IAP) No. DW96945884.

Additionally, Mr. Richard Watkins of the Louisville Metropolitan Sewer District, who performs Operation and Maintenance (O & M) on the site, provided much support for this review. Mr. Ken Logsdon of the Kentucky Division of Waste Management, who oversees O & M activities, provided assistance during the inspection. Finally, Mr. Femi Akindele from Region IV of the U.S.EPA arranged for, and participated in the inspection. A full list of site inspection participants is provided in Attachment C-1.

Other Review Characteristics

This is the third Five-Year review for the Lee's Lane Landfill. The triggering action for this review is the final report of the Second Five-Year Review dated 06/30/98, as shown in EPA's WasteLAN database. Since the landfill waste was, for the most part, left in place, the selected remedy requires continual operation of a subsurface gas collection and venting system to prevent migration of landfill-generated gases into an adjacent residential area. Additionally, ground water wells, gas wells, ambient air, settlement plates, and surface conditions are monitored to determine the adequacy of the site's remedial measures. Therefore, a review is required to be conducted at least every five years.

II. Site Chronology

Table 1: Chronology of Site Events

Event	Date
Flash fires around residential water heaters due to migration of methane gas from the landfill	Early 1975
Gas subsurface venting system installed by KY Dept of Hazardous Materials and Waste Management	10/1980
Listed on NPL	09/08/1983
Remedial Investigation/Feasibility Study complete	04/1986
Enforcement Decision Document (EDD)	09/1986
EPA completed response actions according to EDD	03/18/1988
O&M transferred from EPA to MSD	07/16/1991
1 st Five-year review report	03/11/1993
Site Review and Update by ATSDR	09/30/1993
Oversight of MSD's O&M transferred to KNREPC	04/07/1994
Delisted from NPL	04/25/1996
2 nd five-year review report	06/30/1998

III. Background

Physical Characteristics

The Lee's Lane Landfill site is located in the City of Louisville, Jefferson County, Kentucky and is 112 acres in size. The site is located on the southeast bank of the Ohio River from approximate river mile 615.35 to 616.2 and lies between the river and the Louisville Levee. The site location is shown on Figure 1, and a recent aerial view of the landfill is provided as Figure 7. The entire site is approximately 5,000 feet long and 1,500 feet wide. As indicated on Figures 2 and 3, the landfill is divided into three portions, a northern tract, central tract, and southern tract. The Northern and Central Tracts of the landfill consist of level to gently sloping land, while the Southern Tract contains two depressions with steep slopes. Much of the landfill surface is covered with well-established vegetation ranging from brush to woodlands. Elevations range from 383 feet above mean sea level along the Ohio River to 461 feet at the top of the levee. The geology of the site consists of approximately 110 feet of Ohio River alluvium (20 - 30 feet of silts and clay over 80-90 feet of sand with varying amounts of gravel), see Figure 6. Underlying the river alluvium is the New Albany Shale. The alluvial aquifer is unconfined with the shale forming an aquitard between the alluvial aquifer and the deep limestone aquifers. The water table is approximately 50 feet below the surface. Flow in the aquifer is predominantly toward the Ohio River. During periods of high river flow, however, groundwater flow direction may reverse. Water levels in the aquifer vary with fluctuations of the Ohio River.

Land and Resource Use

The landfill is bounded on the northeast by the Borden, Inc. chemical plant; on the southeast by the Louisville Flood Protection Levee and thence the residential area of Riverside Gardens, which contains about 330 homes; on the southwest by the Louisville Gas and Electric Company Mill Creek Pump Plant; and along the northwest boundary by the Ohio River.

Prior to 1993, there were a small number of private drinking water wells located in the Riverside Garden subdivision. However, since at least 1993, the entire subdivision has been supplied public water by the Louisville Water Company.

Although most of the natural plant communities at the site have been disturbed, a good secondary growth of grasses and shrubs have developed over the Northern and Central Tracts, while a low-lying area in the Southern Tract has developed into a wetland and open water area. Additionally, a dense growth of vegetation characteristic of riparian woods exists along the Ohio River. The diversity of habitats at the site suggests the area could contain an abundant faunal population. Small mammals are expected to dominate the woodland and brush areas. These areas would also be conducive to birdlife. Aquatic life in the Ohio River near the site is dominated by pollution-tolerant species.

History of Contamination

Domestic, commercial, and industrial wastes were disposed of in the landfill from the late 1940's to 1975. Prior to and during its use as a landfill, sand and gravel were quarried at the site. In 1971, the State of KY permitted the Southern Tract of the landfill under its Solid Waste Program. In 1974, the Lee's Lane Landfill permit expired and, due to repeated compliance violations, was not renewed.

In March 1975, the Jefferson County Department of Public Health was notified of the presence of methane gas in the Riverside Gardens subdivision. As a result of explosive levels of methane gas, seven families along the street closest to the landfill were evacuated by the Jefferson County Housing Authority. In April 1975, the KY Natural Resources and Environmental Protection Cabinet filed a lawsuit against the landfill owners. This resulted in the closure of the landfill in the same year.

Initial Response

Between 1975 and 1979, 44 gas observation wells were installed in and around the landfill and in Riverside Gardens to monitor the concentration, pressure and lateral extent of methane gas migration. Samples collected from these wells indicted that the source of the methane and associated toxic gases was the decomposition of landfill wastes. In October 1980, a gas collection system was designed and installed on the site by SCS Engineers, between the landfill and Riverside Gardens.

In November 1978, the Surveillance and Analysis Division (SAD) of the Kentucky Division of Waste Management collected samples from residential wells in Riverside Gardens to determine the potential effects of the landfill on groundwater quality. As a result of the study, the SAD reported that there was no indication of the migration of contaminated groundwater from the landfill to the residential wells.

In February 1980, the KY Department of Hazardous Materials and Waste Management discovered approximately 400 drums about 100 feet from the Ohio River bank on a 10-foot vertical rise above the river. In September and October of 1981, the drums were removed by the landfill owners under Court Order. The wastes were removed from the drums and transported to an approved hazardous waste disposal facility. The remaining non-hazardous drummed materials and empty drums were buried onsite.

In early 1981, the Kentucky Natural Resources and Environmental Protection Cabinet (KNREPC) installed eleven shallow groundwater monitoring wells at the site. Five of these were later sampled by EPA. Analyses of the samples indicated that the on-site groundwater contained inorganic compounds at elevated concentrations. However the results were believed to be affected by the presence of sediment in the wells, apparently due to improper well completion.

Basis for Taking Action

In December 1982, the EPA evaluated the Lee's Lane Landfill Site using the Hazard Ranking System (HRS) as described in the National Oil and Hazardous Substances Pollution Contingency Plan (NCP). The overall score was 47.46 which ranked the site high enough to be placed on the National Priorities List (NPL). The site received a high score because of its distance from the nearest population (300 feet), the floodway location, the identification of landfill hazardous wastes, particularly chromium and vinyl chloride, and the close proximity to the nearest well in Riverside Gardens.

The Remedial Investigation/Feasibility Study (RI/FS) completed in April 1986 concluded as follows:

- The onsite migration pathways consisted of surface water infiltration to groundwater in the Northern and Central Tracts, with minimum runoff and ponding except during major storms and floods. Surface water infiltration was also expected in the Southern Tract, but runoff to the large pond was a probable pathway due to the steep slopes.

- Onsite surface water contained very low levels of contaminants. Onsite soils and sediments were similar to the offsite background sample collected in Riverside Gardens, suggesting the use of local soils as cover material. In two areas where "hot spot" soil samples were collected, the estimated concentrations of lead and chromium were 2,000 mg/kg each. These areas were located along the access road in the Central Tract and were believed to be the result of indiscriminate dumping since the concentrations found were not representative of overall soil concentrations.

- The major migration pathway for groundwater was direct discharge to the Ohio River. The groundwater discharge from the landfill to the Ohio River was estimated at 0.0015 % of the total Ohio River flow. If high water conditions on the Ohio River were to exist for a sufficient period of time, groundwater reversal might occur and flow would be toward the Riverside Gardens residential wells. Additionally, the effects of contaminant migration under the Ohio River were expected to be inconsequential.

- Onsite groundwater contained low levels of organic compounds and some inorganic contaminants. The major inorganic compounds included arsenic, barium, cadmium, chromium, lead, manganese, and iron. The offsite concentrations of these contaminants were below the maximum contaminant levels (MCL) set in the Interim Primary Drinking Water Regulations. Neither manganese nor iron was considered to pose significant health risks.

- The IT Corporation evaluated the existing subsurface gas collection system and concluded that the system was operating at less than 50% efficiency. Gas monitoring indicated, however, that it was still mitigating gas migration. In November 1985, the Jefferson County Department of Public Works contracted SCS Engineers to inspect the gas collection system. Repairs of problem areas noted were completed in 1986.

- The public health assessment concluded that the primary health concern at the site was the elevated chromium levels found in onsite groundwater. Need for groundwater remediation was not indicated by the public health assessment. However, long-term monitoring of groundwater and ambient air was recommended to establish baseline conditions and to serve as an early detection system should site conditions change.

- There was no evidence of an offsite public health or environmental problem related to the site based on available information.

- The public health assessment indicated that the existing gas collection system was mitigating gas migration, but that the system needed to be repaired or replaced. A routine subsurface gas monitoring program also needed to be implemented outside the collection system and in Riverside Gardens.

- The public health assessment also noted that, in the absence of controlled access to the site, the surface wastes should be removed and the soils containing elevated levels of chromium and lead should be covered.

IV. Remedial Actions

Enforcement Decision Document (EDD)

The EPA signed an Enforcement Decision Document (EDD) on September 25, 1986, for the Lee's Lane Landfill. The document provided for the following response actions:

- 1 Inspection, repair, and operation of the gas collection system,
- 2 Provision for alternate water supplies for residences still on wells,
- 3 Removal of exposed drums,
- 4 Capping with soils in "hot spots" in an area of exposed trash and disposal of exposed wastes
- 5 Imposition of institutional controls, including security gates and cautionary signs,
- 6 Construction of a rip-rap slope along the Ohio River bank,
- 7 Repair of an existing drainage ditch and installation of a 20-inch drainage pipe,
- 8 Monitoring of groundwater wells, gas wells, and ambient air, and
- 9 Operation and maintenance activities to include inspection of the gas monitoring wells, the gas collection system, capped waste areas and the riprap along the Ohio River bank.

Remedy Implementation

On March 10, 1987, the EPA initiated a removal action in accordance with the EDD, as described above. The removal action was completed on March 18, 1988.

System Operation/Operation and Maintenance (O & M)

The EPA performed operation and maintenance from July 1988 to June 1989. On July 16, 1991, the EPA issued an Administrative Order of Consent under which the Louisville and Jefferson County

Metropolitan Sewer District (MSD), agreed to perform certain O&M activities at the site for twenty-nine (29) years. On April 7, 1994, the Commonwealth of Kentucky entered into an Intergovernmental Response Agreement with the EPA under which Kentucky assumed responsibility for the oversight of MSD's O&M activities.

MSD performs many of its required O&M activities by its own in-house staff and does not track the costs of the efforts. However, subcontractor costs for monitoring survey monuments, groundwater sampling and analyses, and gas monitoring are approximately \$18,000 per year.

V. Progress Since the Last Review

The second Five-Year Review report for the Lee's Lane remedial action was signed on June 30, 1998. The report concluded that the response action by EPA remained protective of human health and the environment, but that the gas collection system required maintenance. The recommended actions and accomplishments are as follows:

The gas collection system should be checked for proper operation and serviced as necessary. To date, this has not been accomplished.

Install better security measures, including barricades to deter site access. The lock at the Lee's Lane has been restored and the gates maintained, however, there still exists much four-wheel driver trespassing.

Fill low areas along the access road. Some areas have been filled with gravel.

Mow grass on a regular basis. Grass is mowed five times a year when performing similar mowing along the adjacent flood control levee.

Establish and maintain a proper ground survey to monitor ground movements within the area of riprap along the Ohio River bank. A survey of the subject monuments has been completed recently and another is scheduled for 2004.

Remove and properly dispose of an on-site 20,000 gallon underground storage tank (UST). This has been done.

Continue air and gas well sampling on a quarterly basis and groundwater monitoring on an annual basis. Although several of these monitoring events were not performed, such monitoring has been conducted for 2000, 2001, and 2002.

Continue quarterly site inspections. These are done regularly.

VI. Five-Year Review Process

Administrative Components

In November 2002, Mr. Femi Akindale of the EPA requested the assistance of the U.S. Army Corps of Engineers in performing the third Five-Year review of the subject project. Hard copies of the major project documents could not be located either with MSD or at the Site Repository indicated on EPA websites. Subsequently, Mr. Akindale provided copies, via compact disc, of most of the project documents to the Corps in early-December 2002. In mid-December 2002, Messrs Nathaniel Peters and John Jent met with Mr. Richard Watkins at the MSD facility to discuss available documentation and to receive a brief overview of the site. Some additional documentation, mostly maps, were provided by Mr. Watkins at that time. In January, the Corps asked for and received documentation of historic sampling and analysis results from KNREPC, which MSD currently did not have. In mid-January 2003, representatives of the EPA, the Army Corps of Engineers, MSD, and the KNREPC established the following schedule:

Document Review	Mid Jan - Mid Feb
Data Review	Mid Jan - Mid Feb
Site Inspection	February 25, 2003
Telephone Interviews	March 2003
Five-Year Draft Report	April 4, 2003
Five-Year Final Report	May 9, 2003.

Document Review

This five-year review consisted of a review of the RI, the EDD, the first and second five-year review reports, a Site Review and Update conducted by the Agency for Toxic Substances and Disease Registry (ATSDR), and the MSD Guidance for Institutional Inspection, Monitoring, Maintenance and Operation Activities.

ARARs Review

A review of the Applicable or Relevant and Appropriate Requirements (ARARs) was conducted by the U.S. Army Corps of Engineers Center of HTRW Expertise, and its review follows.

The September 1986 EDD identified the following ARARs for the site:

- 40 CFR 263, Standards Applicable to Transporters of Hazardous Waste
- 40 CFR 264, Subpart F Groundwater Protection Standards
- 40 CFR 264, Subpart F Alternate Concentration Limit (ACL) provisions

The 40 CFR 263 standards for hazardous waste transporters applied during the drum/waste removal portion of the cleanup. Therefore, they are no longer germane to current activities at the site and are not further evaluated in this report.

In June of 1987, EPA established ACLs for the site. This established new (and higher) values for site contaminants than provided for in the 40 CFR 264 groundwater protection standards. The ACLs were developed by multiplying the applicable surface water quality standard for each contaminant of concern by the magnitude of dilution occurring when groundwater beneath the site discharges to the Ohio River. The previous dilution factor was 1,300, based on the minimum guaranteed flow downstream of Louisville, KY provided by the Corps of Engineers in 1987. In March 2003, the Hydraulics Branch of the U.S. Army Corps of Engineers (Louisville District) provided a 7-day, 10-year statistical low flow rate of 11,000 cubic feet per second (cfs). Groundwater discharges at a rate of 10 cfs along the Ohio River side of the site. Therefore, a dilution factor of 1,100 was used to establish a new set of ACLs. The 1987 Kentucky water quality standards used to establish ACLs are listed along with the current values in the following table:

Table 2 COMPARISON OF PREVIOUS ACLs TO NEW STANDARDS ¹						
Contaminant	Basis ²	Old Standard ³ (mg/l)	Old ACL (mg/l)	New Standard ⁵ (mg/l)	New ACL ¹⁰ (Drought) (mg/l)	New ACL ¹¹ (Lowest Seasonal) (mg/l)
	Ohio River Flow (cfs)		13,000 ⁴		11,000	30,700
	Dilution Factor		1,300		1,100	3,070
Arsenic	WAH	0.05	65	0.050	55	153.5
Barium	DWS	1.00	1300	2.0	2200	6140
Beryllium	DWS	1.10	1430	0.000004 ⁷	0.0044	.01228
Cadmium ⁶	WAH	0.012	15.6	0.0032	3.52	9.824
Hexavalent Chromium	OMS	0.05	65	0.016	17.6	49.12
Copper ⁶	OMS	0.022	28.6	0.012	13.2	36.84
Iron	WAH	1.00	1300	1.00	1100	3070
Lead (dissolved) ⁶	OMS	0.05	65	0.0049	5.39	15.043
Manganese	DWS	0.05	65	0.05	55	153.5
Mercury	WAH	0.0002	0.26	0.00091	1.01	2.7937
Selenium	DWS	0.01	13	0.05	55	153.5
Zinc ⁶	WAH	0.07	91	0.159	174.9	488.13
Benzene	CAG	0.0012 ⁸	1.56	0.0012 ⁹	1.32	3.684

- 1 - A change in a standard resulting in a new ACL value that is lower than the previous ACL value has been bolded and highlighted.
- 2 - WAH = Warm Water Aquatic Habitat
DWS = Drinking Water Supply (applicable at existing points of public water supply)
OMS = Standards applicable specifically to the main stem of the Ohio River
CAG = Cancer Advisory Group, EPA HQ
- 3 - The old standards listed are those provided in the 1993 Review of Response Action Report used to initially establish ACLs.
- 4 - Corps of Engineers minimum guaranteed flow downstream of Louisville, 13,000 cfs (1987).
- 5 - New Standards reflect current values in Kentucky Water Quality Standards regulations at 401 KAR 5:031.
- 6 - Values for these contaminants determined assuming a hardness of 140 per the previous review reports.
- 7 - Kentucky no longer has a WAH value for beryllium, therefore the current value used is from the DWS standard.
- 8 - The old value for benzene came from the Cancer Assessment Group at EPA HQ.
- 9 - The current standard is from the Kentucky DWS standard.
- 10- Corps of Engineers 7-day, 10-year statistical Ohio River flow rate, 11,000 cfs, computed in 2003.
- 11- Corps of Engineers lowest seasonal Ohio River flow rate, 30,700 cfs, computed in 2003.

Based upon changes to the Kentucky Surface Water Quality Standards, the ACLs have changed to significantly lower values for beryllium, cadmium, hexavalent chromium, copper and lead. Changes in standards have resulted in higher ACLs for barium, mercury, zinc, and selenium. While the standards for arsenic, iron, manganese and benzene have not changed, the change in the dilution factor from 1300 in 1987 to 1100 in 2003 resulted in lower ACLs for these contaminants.

Groundwater sampling data through April 2001 shows no apparent exceedances of the lower ACLs with the possible exception of beryllium. The new DWS standard for beryllium has resulted in a significantly lower ACL (from 1430 mg/l to 0.0044 mg/l). Groundwater data shows that sampling and analysis for beryllium is not being done at the site. Due to the extremely low ACL of 0.0044 mg/l, it is recommended that future groundwater sampling efforts include analysis for beryllium in order to demonstrate compliance with the ACL. When decision limits are re-evaluated, the adequacy of the analytical methodology to monitor the contaminants of concern with respect to the new decision limits should be specified.

Option to Recalculate ACLs Based Upon Historical River Flow Rate Data: EPA may wish to give consideration to reevaluating how the ACLs are calculated. To date, a historical low flow rate has been used. While very conservative in that it represents the very worst case scenario in river flow rates, it may be more realistic to use the most recent low season flow rate. A flow rate of 11,000 cfs represents a drought year. During drought years, the groundwater discharge rate will also be reduced. The Hydraulics Branch of the U.S. Army Corps of Engineers (Louisville District) provided the following flow rates for water years (WY) 1929 - 2001 for the Ohio River:

Ohio River Flow Rates*

Increment	WY 2001	WY1929-2001
Yearly	87,400cfs	115,700cfs
Winter	109,200cfs	160,200cfs
Spring	141,500cfs	196,100cfs
Summer	70,300cfs	61,900cfs
Fall	30,700cfs	46,000cfs

* Data taken downstream of the McAlpine Dam at approximately river mile 607.

Based upon this data, a more appropriate Ohio River flow rate of 30,700 cfs, the lowest seasonal flow, could be utilized to determine a dilution factor of 3,070 to calculate ACLs. While not

as conservative as the 1,100 dilution factor, it is more representative of actual flow conditions of the Ohio River.

Data Review

Data from several reports included in Attachment C were reviewed and analyzed as follows:

Attachment C-2, the checklist for the site inspection of February 25, 2003, prepared by MSD. The report indicated no distress to physical features such as ditches, rip-rap, and roads.

Attachment C-3 provides tabulations of groundwater contaminant concentrations in relation to performance standards for GW MWS-A,B,02, 04 and 05. Comparison of the contaminant concentrations from GW MWS-A,B,02 shows consistent detections above the SMCLs for iron and manganese, and a single detection above the MCL for antimony and cadmium. For GW MWS-04,05 and from 1995, there have been no detections of the contaminants of concern in the EDD, above the new, conservatively calculated ACLs. Beryllium, copper, hexavalent chromium, and filtered lead should be added to all future analyses of groundwater from these two monitoring wells.

Attachment C-4 provides tabulations of gas concentrations from the five gas monitoring wells (G-1,2,3,4,5) in relation to the 25% lower explosive limit (LEL). All readings were well below the 25% LEL, however, the levels of methane have dramatically increased since 1997. A plot of methane concentrations at these wells is provided as Attachment C-6.

Attachment C-5 provides tabulations of gas concentrations from the six current ambient air monitoring stations (R1, R2,R3,U1, A1, A2) in relation to the 25% lower explosive limit (LEL). All readings were well below the 25% LEL, however, the levels of methane have dramatically increased since 1997. A plot of methane concentrations at the ambient air sampling locations is provided as Attachment C-7.

Site Inspection

Inspection of the site was conducted on February 25, 2003 by representatives of the EPA, the KNREPC, the MSD, and the U.S. Army Corps of Engineers. The purpose of the inspection was to assess the protectiveness of the remedy, including the adequacy of site security measures. A complete list of inspection attendees is provided in Attachment C-1. Initially, the inspection team met off site at the main MSD maintenance facility, and the team was provided an overview of the remediation, monitoring, and O & M

activities that have been done. Temperature on the day of the inspection was about 20° F and there was a small amount of snow cover. Leaves and other vegetation had not developed and thus there was good visibility of the surface within wooded and brushy areas.

The pre-inspection briefing greatly facilitated understanding of the uniqueness of the site's contamination and associated remedial action. Additionally, on May 15, 2003, Messrs. Mathew Przystal of the Louisville Health Department, Richard Watkins of the Louisville Metropolitan Sewer District, and John Jent of the U.S. Army Corps of Engineers visited the site to document the presence of an elastic material noted at two locations within the landfill by Mr. Przystal. The following items were noted and comments made during the inspections: Figures and photos are included in Attachments A and B.

1. The access gate across the Lee's Lane entrance appears to be in good condition. It prevents motor vehicles from entering, but quad-runner ATVs can very easily go around the gates, see Photograph 1 and Figure 4.
2. The levee itself appears to be in good condition. It was constructed on original materials landward of the landfill, and has relatively flat, well maintained slopes. There is a newly constructed asphalt path on the levee South of Lee's Lane. At Lee's Lane, the path turns away from the levee and proceeds northeasterly along Lee's Lane, see Photograph 2 and Figure 4.
3. Although motor vehicles cannot travel along the asphalt path, pedestrians and quad-runner ATVs can. Cracking of the pavement indicates that it will begin to deteriorate rapidly under heavy traffic, see Photographs 5 and 6.
4. The ditch that extends approximately along the line of the subsurface gas collection wells has no outlet and thus ponds water. Based on a topographic map from 1961, Figure 8, drainage from this ditch was blocked by filling of the landfill within the Central Tract. In some cases, the level of the ponded water is above the top of individual gas collection wells, see Photographs 2,3,4 and Figures 4,5, and 8.
5. The wooded area between the gas collection system and the capped area is very rough and hummocky, see Photograph 7.
6. The rock-lined ditch at the north end of the rip-rap appears in good condition. The wooded area (Northern Tract) directly

north of the ditch appeared stable and little or no rubbish was present on the surface, see Photograph 8 and Figure 2.

7. The rip-rap placed at the Ohio River bank along the Central Tract appears very stable, unweathered and of adequate size. No erosional activities or seeps were noted along the river bank. Small amounts of brush were present at the base of the rip-rap along the river, see Photograph 9.
8. As shown in photographs 10 A and B, settlement monuments within and outside the rip-rap area appeared to be stable.
9. The capped area immediately landward of the rip-rap appeared relatively flat with no major surface depressions observed. There was some severe rutting across the cap due to uncontrolled, trespasser, quad-runner ATV traffic, see Photograph 11.
10. Sediment and debris have blocked the shale-lined ditch across the capped area where it meets the rip-rap area, see Photograph 12 and Figure 4.
11. The corrugated metal pipe beneath the access road at the shale-lined ditch has a large amount of sediment buildup at its downstream end and thus ponds water at the upper end, see Photographs 13 A,B and Figure 4.
12. The access road to the South Tract has only a thin cover of gravel and is severely rutted, due mostly to the uncontrolled trespasser quad-runner ATV traffic, see Photograph 14 and Figure 2.
13. The South Tract is somewhat hummocky and contains a fairly dense group of trees and debris.
14. Uncontrolled trespasser quad-runner ATV traffic has created many ruts and large bare areas adjacent to both sides of Putnam Street at the riverside toe of the levee. Additionally, there is a rather large pond about 300 feet in diameter that poses a danger to trespassers, see Photograph 16.
15. Although there appears to be much uncontrolled trespassing, the site gas and groundwater monitoring wells, the gas collection wells, the gas collection blower house, and the settlement monuments do not appear to have been interfered with by trespassers.

16. The blower house for the subsurface gas collection system has many pipes and controls. Mr. Mike Humphrey of MSD indicated that the only maintenance that MSD performs is to replace burnt-out motors. The system runs continuously. He said MSD has no operations and maintenance manual for the system, no as-built drawings, and generally has no way of adequately monitoring the performance of the system, see Photographs 4 and 17, and Figure 5.
17. Traffic access to the landfill via Putnam Road is blocked by a guard rail barrier as shown in Photograph 18.
18. A water meter and a fire hydrant present along Putnam Road indicate that municipal water is available to local residents.
19. On May 15, 2003 an elastic material, possibly a resin, was noted at the surface of the landfill at the location noted on Figure 4 and Photographs 20 A,B. The surface lateral extent was approximately 3' wide by 10' long, and the material extended about a foot above the adjacent surface. No odors were noted.
20. On May 15, 2003 the remains of a buried 55-gallon drum with material similar to that noted in 19 above was noted at the location shown on Figure 4 and Photograph 21.

Site Inspection Summary

1. Although the MSD is responsibly and aggressively performing O&M of the landfill, it has been hampered by not having key project documents in its custody for reference by those in charge of the field equipment. The O&M manual and as-built drawings for the subsurface gas collection system should be readily available to MSD.
2. Site security issues have historically been a major problem and are currently of concern. Uncontrolled trespasser quad-runner ATV traffic significantly degrades site access, could destroy surface cover, and could be a significant liability issue. Although, there is no known damage to the site due to trespassers to date, there is a high potential for vandalism to site facilities such as the monitoring wells and monitoring equipment. In addition, the recent construction of a new asphalt pedestrian pathway by the City of Louisville along the levee at the site provides a new environmental exposure route and possible safety and liability issues. The MSD, the City of Louisville, and the EPA need to evaluate the adequacy of current site security and

potential liabilities associated with the present situation of easy access to the site.

3. Other major components of the remediation, such as the rip-rap erosion protection along the Ohio River bank, the clay cap over the landfill, and the on-going monitoring activities are satisfactory at this time.

4. Several drainage related concerns were observed, including:

- A. Sediment build-up within the corrugated metal pipe along the shale-lined drain beneath the access road across the clay cap, and poor grade in the ditch where it intersects the rip-rap area to facilitate drainage down the rip-rap slope.
- B. Inadequate outfall for the ditch adjacent to the line of subsurface gas collection wells.

5. The access road through the South Tract is currently barely passable due to a combination of its steep slope and trespasser quad-runner ATV traffic.

6. The elastic material noted at two locations within the landfill needs to be sampled and analyzed to determine its potential for adverse human health or ecological effects.

Additional Inquiry

Following the site inspection, contact was made with Mr. James J. Walsh of SCS Engineers to discuss the current situation. SCS Engineers was the firm that initially designed and installed the subsurface gas collection system and later repaired it. Mr. Walsh provided a letter describing his company's involvement and recommended that the subsurface gas collection system be thoroughly investigated at the earliest possible date. A copy of this correspondence is provided as Attachment C-9.

Community Involvement Activities

In March 2003, the US EPA announced that the remedy at the site was under review in the local newspaper, conducted telephone interviews with local residents and invited comments on activities related to the site. Responses to the interviews were mixed. Some people were pleased overall and some expressed displeasure with the method and extent of the cleanup implemented at the site. In any case, no one identified a specific problem to indicate that the objectives of the remedy at the site are not being met currently. Copies of the telephone interviews are in Attachment C-8. One interviewee noted an elastic material present at two locations

within the landfill. These two locations were inspected, and the material observed did not appear to be of any significance relative to the remedial action in place.

VII. Technical Assessment

Question A: Is the remedy functioning as intended by the decision documents ?

The review of documents, ARARs, risk assumptions, groundwater and gas monitoring well data, and the results of the site inspection indicate that the remedy has functioned to this point as intended by the EDD. The remedial actions have achieved the remedial objectives of preventing the migration of potentially explosive gases from the landfill to the Riverside Gardens subdivision, minimizing on-site exposure, minimizing off-site exposure, and providing adequate level of site security. The connection of all Riverside Gardens subdivision residents to municipal water has significantly reduced environmental risk to the adjacent residents. Increasing concentrations of methane gas levels in both the gas monitoring wells and ambient air sampling, however, indicate a very strong need for an extensive evaluation of the subsurface gas collection system.

Although the MSD is attempting to responsibly and aggressively perform O&M of the landfill, it has to this point been hampered by not having key project documentation in the possession of those now charged with performing the O&M. The MSD should have in its possession an operations and maintenance manual and as-built drawings for the subsurface gas collection system, the key component of the remedial action. Contact and coordination with the firm that constructed the subsurface gas collection system should be done at the earliest possible time. The MSD is currently doing an excellent job of performing the required site inspections and facilitating the required groundwater and gas sampling and analysis. However, the results of the sampling analyses need to be better evaluated, both within the context of historical data to determine trends, and within the regulatory context, relative to the ACLs and 25% LELs, to ensure that measured levels are below action levels.

Although the MSD has taken every practical measure to provide site security, the construction of a pedestrian path along the levee top and the large amount of uncontrolled trespasser quad-runner ATV traffic require that the MSD, the City of Louisville, and the EPA further consider the limits and ramifications of site security measures.

Question B: Are the exposure assumptions, toxicity data, cleanup levels, and remedial action objectives (RAOs) used at the time of the remedy selection still valid ?

The connection of all Riverside Gardens residents to municipal water supply has removed the groundwater exposure scenario for nearby residents. An ARARs review conducted by the U.S. Army HTRW Center of Expertise, provided new Alternate Concentration Limits (ACLs⁵) to be utilized for groundwater monitoring wells MW-4 and MW-5, i.e., the two wells being monitored for groundwater flow into the Ohio River. This re-analysis is provided in the ARARs Review above. Since all residents adjacent to the project are now connected to a municipal water supply, there is no need to continue monitoring Groundwater Wells MWs-A, B, and 02 since there is no longer a complete pathway for groundwater exposure.

New Kentucky Water Quality Standards require additional laboratory analyses for the groundwater samples from Groundwater MWs-04,05. Based on the review of ARARs, future groundwater samples should be analyzed for beryllium and copper, hexavalent chromium (instead of total chromium) and filtered lead (instead of total lead) in addition to those analyses currently specified. When decision limits are re-evaluated the adequacy of the analytical methodology to monitor the contaminants of concern with respect to the new decision limits should be evaluated. Finally, updated exposure parameters and human health risks may need to be developed for the site in view of the newly constructed path at the top of the levee. Additionally, the MSD, the City of Louisville, and the EPA need to re-evaluate the risks and liabilities, both environmental and safety, due to the uncontrolled trespasser quad-runner ATV traffic.

Question C: Has any other information come to light that could call into question the protectiveness of the remedy ?

Increasing concentrations of methane gas levels, in both the gas monitoring wells and ambient air sampling, indicate the need for an extensive evaluation of the subsurface gas collection system. Mr. James J. Walsh of SCS Engineers, the firm that initially designed, installed, and later repaired the subsurface gas collection system, recommended that the subsurface gas collection system be thoroughly investigated at the earliest possible date to determine if the system is adequately preventing potentially explosive gases from migrating from the landfill to the Riverside Gardens subdivision.

Technical Assessment Summary

The remedial actions at this site to date have achieved the remedial objectives of preventing the migration of explosive gases from the landfill to the Riverside Gardens subdivision, minimizing on-site exposure, minimizing off-site exposure, and providing adequate level of site security. Connection of all Riverside Gardens subdivision residents to municipal water has significantly reduced environmental risk to the adjacent residents. However, increasing concentrations of methane gas in both the gas monitoring wells and ambient air sampling, in addition to the opinion of the remediation system's designer, indicate a strong need for a comprehensive evaluation of the subsurface gas collection system. Appropriate measures, limits, and liabilities associated with new pedestrian traffic adjacent to the landfill and uncontrolled trespasser quad-runner ATV traffic need to be evaluated by the MSD, the City of Louisville, and the EPA.

VIII. Issues

Table 3 Issues	Affects Current Protectiveness (Y / N)	Affects Future Protectiveness (Y / N)
Project documentation is not available to the project operators.	N	Y
Although measured methane gas levels are still below the ARARs limits, recent dramatic increases in those levels question the adequacy of the subsurface gas collection system.	N	Y
The main drainage way across the capped portion of the landfill is blocked.	N	Y
The access road to the Southern Tract is almost impassable.	N	Y
Pedestrian flow across a newly constructed walkway along the levee adjacent to the project and significant trespasser incidence present liability problems for the agencies charged with overseeing the project.	N	Y
New Kentucky Water Quality Standards require additional analyses for the groundwater samples from Groundwater MWs-04,05.	N	Y
Since all residents adjacent to the project are now connected to a municipal water supply, there is no longer a need to sample/analyze groundwater from Groundwater MWs-A, B and 02.	N	N

IX. Recommendations and Follow-up Actions

1. Maintain already programmed O&M activities currently undertaken by MSD and increase the oversight by KNEPC.
2. Proactively address issues listed in Tables 3 and 4 of this report.

Table 4: Recommendations and Follow-up Actions

Issue	Recommendations and Follow-up Actions	Party Responsible	Oversight Agency	Milestone Date	Affects Protectiveness (Y/N)	
					Current	Future
1	Complete Re-Evaluation of the Subsurface Gas Collection System	MSD/ KNREPC	EPA	Dec 2003	N	Y
2	Re-Evaluate Site Security Measures, Limits, and Liabilities	MSD/City of Louisville / KNREPC	EPA	Dec 2003	N	Y
3	Improve Site Drainage (Ditch Along Line of Wells & Blocked Ditch & Drain Pipe Under Access Road)	MSD	EPA/ KNREPC	Dec 2003	N	Y
4	Evaluate Site Monitoring Data	MSD	KNREPC	Dec 2003	N	Y
5	Re-Establish Information Repository (possibly at MSD Maintenance Bldg)	MSD	KNREPC	Dec 2003	N	Y
6	Develop Coordination Plan to Implement (1-5)	MSD	KNREPC	Sep 2003	N	Y
7	Discontinue Sampling of GW MWs-A, B, and 02	MSD	KNREPC	Present	N	N
8	Add Laboratory Analyses as Required by New KY Water Quality Standards on Samples from GW MWs-04,05	MSD	KNREPC	Present	N	Y

X. Protectiveness Statement

The remedy at the Lee's Lane Landfill currently protects human health and the environment, because it significantly reduces the migration of explosive gases from the landfill and minimizes on-site and off-site exposure to contamination. In order for the remedy to be protective in the long-term, a re-evaluation of the subsurface gas collection system is recommended by December 2003, and any necessary repairs to the system should be initiated as soon as possible. Although every practical site security measure has been taken, the limits and liabilities of current measures need to be re-evaluated in terms of pedestrian traffic adjacent to the landfill and the uncontrolled trespasser quad-runner ATV traffic.

XI. Next Review

The next Five-Year Review is due by June 30, 2008.

Attachment A Figures

Figure 1	Site Map
Figure 2	Site Layout
Figure 3	Monitoring Locations
Figure 4	Site Inspection Map
Figure 5	Subsurface Gas Collection System
Figure 6	Cross-Section of Landfill
Figure 7	1998 Aerial Photograph of Site
Figure 8	1961 Topographic Map of Site
Figure 9(A-E)	Descriptions of Landfill Sections

Attachment B Photographs

Photograph 1	Entrance Gate at Lee's Lane
Photograph 2	View Looking North Along the Levee from the Lee's Lane Crossing
Photograph 3	Top of Gas Collection Well #28 Under Water Ponded in the Ditch Parallel to the Line of Gas Collection Wells
Photograph 4	Blower House and Gas Collection Wells from Lee's Lane
Photograph 5A,B	View Looking South Along the Levee from the Lee's Lane Crossing
Photograph 6	Approach to Landfill Along Lee's Lane
Photograph 7	Central Track Wooded, Hummocky Area
Photograph 8	Rock-Lined Ditch at North End of Central Tract and Wooded Northern Tract
Photograph 9	Rip-Rap Bank Protection
Photograph 10	Settlement Monuments
Photograph 11	Ruts Along Capped Area
Photograph 12	Blocked Shale-Lined Drainage Ditch Across Capped Area at the Top of the Rip-Rapped Slope
Photograph 13A,B	Ponded Water Upstream of Drainage Pipe Blockage
Photograph 14	Access Road in Southern Tract
Photograph 15A,B	Debris and Hummocky Surface in Southern Tract
Photograph 16	Ruts and Eroded Surface Due to Quad-runner ATV Traffic; View from Putman Road Looking South

Photograph 17 Piping at the Subsurface Gas Collection Blower
House
Photograph 18 Barrier Across Putnam Road
Photograph 19A,B Water Meter and Fire Hydrant Along Putnam Road
Photograph 20A,B Elastic Material Observed at the Surface
Photograph 21 Buried Drum with Elastic Material

Attachment C Forms

- 1 5-Year Review Site Inspection Attendees
- 2 5-Year Review Site Inspection Checklist (from MSD)
- 3 Groundwater Monitoring Data
- 4 Gas Monitoring Well Data
- 5 Ambient Air Monitoring
- 6 Plot of Methane Measurements in Gas Monitoring Wells
- 7 Plot of Methane Measurements in Ambient Air
- 8 Telephone Interviews
- 9 Correspondence with SCS Engineers

Attachment A

Figures





Figure 1
Site Map
Lee's Lane Landfill



- ③ ELASTIC MATERIAL OBSERVED AT SURFACE
- ④ BURIED DRUM WITH ELASTIC MATERIAL

- ② DITCH EXPOSED IN PRE-AREA
- ③ SEDIMENT BURIED ELASTIC DRAINAGE PIPE




Figure 4
Site Inspection Map
Lee's Lane Landfill

SUR: Lee's Lane Landfill
HUB NO: 94-10581-26
DATE: 26 August 1999

WESTON SPER Region IV IAT
ACTIVITY DESCRIPTION: Map of site showing
well locations

LEE 001





FIGURE 6-3

Figure 5
Subsurface Gas Collection System
Lce's Lane Landfill



CROSS-SECTION MW-02 - MW-05
LEES LANE LANDFILL SITE
JEFFERSON COUNTY, KENTUCKY

FIGURE 4-4

Figure 6
Cross-section of Landfill
Lee's Lane Landfill




Figure 7
1998 Aerial Photo of site
Lee's Lane Landfill



Figure 8
1961 Topographic Map of Site
Lee's Lane Landfill

000867
LEE 001



AREAS USED TO CALCULATE FILL VOLUME
LEES LANE LANDFILL SITE
JEFFERSON COUNTY, KENTUCKY

FIGURE 3-9
Figure 9A
Description of Landfill Sections
Lee's Lane Landfill

LEE 001
000868

TABLE 3-2
AREA AND DEPTH VALUES
USED TO CALCULATE WASTE VOLUME
LEES LANE LANDFILL SITE
JEFFERSON COUNTY, KENTUCKY

<u>Section</u>	<u>Estimated Surface Area (acres)</u>	<u>Estimated Waste Depth (feet)</u>	<u>Estimated Volume (cubic yards)</u>
		<u>Northern Tract</u>	
A	3.2	40	206,000
B	6.2	25	250,000
		<u>Central Tract</u>	
C	2.7	5	22,000
D	1.2	5	9,700
E	13.0	25	324,000
F	0.62	20	20,000
G	1.8	20	38,000
H	5.9	20	61,000
		<u>Southern Tract</u>	
I	2.7	25	109,000
J	20.9	25	843,000
K	7.9	25	319,000

Notes: See Figure 3-9.

Figure 9B
Description of Landfill Sections
Lee's Lane Landfill

LEE 001
000869

3.3.1 Northern Tract

The approximate volume of waste in the Northern Tract has been estimated at 2.56×10^5 cubic yards based on the assumptions presented below.

Section A A large magnetic anomaly was delineated in the eastern portion of the Northern Tract. A well log from the installation of a Phase IV gas monitor well by SCS Engineers showed a refuse depth of approximately 40 feet.

Section B Both the historical photographs and the magnetic surveys indicated possible disposal activity in this area. Based on the rapid slope of the land surface near the river as shown on the available topographic maps, the average depth of the fill material in this area was assumed equal to 25 feet.

3.3.2 Central Tract

The approximate volume of waste in the Central Tract has been estimated at 6.95×10^5 cubic yards based on the assumptions presented below:

Sections C,D Most of the northern portion of the Central Tract between the levee and the access road was used as an auto junkyard. It is assumed that the activity in this area was limited to surface storage of junk. The surface scoring and staining liquids seen on several aerial photos was assumed to be due to the moving and storing of old automobiles. It is believed that excavation did not occur in this area. A minimal depth of 5 feet is assumed for these areas to allow for seepage of oils and grease into the soils.

LEE 001

000870

Section E

The southern portion of the Central Tract between the levee and the access road was used for disposal of waste. Since there is evidence of continuous traffic across this section it is assumed that the excavated depth was relatively uniform. Gas monitor wells installed by SCS Engineers in 1979 indicated a refuse depth between 20 and 25 feet below the surface. 25 feet was the depth used to calculate the volume.

Sections F,G,H

Historical photographs indicate that excavation and filling activity occurred in several areas between the access road and the river. A monitor well installed in section F indicates a fill depth of 20 feet. It is assumed that the excavation and fill activity was limited to areas that did not extend beyond the river bank bluff. Therefore, a 20-foot fill depth was assumed for these areas.

3.3.3 Southern Tract

The approximate volume of wastes in the Southern Tract has been estimated as 1.27×10^6 cubic yards based on the assumptions presented below. Because of the size and topography of the two depressions in the Southern Tract, it is believed that wastes were not buried in either of these areas.

Section I

Historical photographs indicate continuous excavation and filling activity. The magnetometer survey showed high anomalous areas. An average depth of 25 feet was assumed based on physical features and topographic information.

Section J

From historical photographs this area was, apparently, where most of the mining operations occurred after

Figure 9D
Description of Landfill Sections
Lee's Lane Landfill

LEE 001

000871

1950. Present topographic information and suspected slope of the pit during activity suggest an average fill depth of 25 feet within this section.

Section K

Historical photographic interpretation shows excavation and fill activity were limited to areas off the river bank. Topographic information and physical features indicate a possible fill depth of 25 feet.

3.6 Waste Containment

Containment of leachate generated by the wastes can not be expected based on the available information concerning the geologic conditions and operation of the landfill site. There are no known liners or leachate collection systems currently in operation at the site. The natural materials in the alluvial aquifer beneath the landfilled area were estimated to have a permeability of 2.99×10^{-3} cm/sec based upon in-situ hydraulic conductivity tests conducted on MW-04 (see Section 4.3.4.2 the discussion of permeabilities.) The soils above the aquifer are estimated to be an order of magnitude less permeable than the alluvial aquifer.

Observations recorded during the RI noted the apparent continued subsidence of the landfill as evidenced by relatively large depressions in the access road. These observations suggest that compaction may still be occurring at the site.

Since there are no available measurements on the permeability of the cover material at the landfill, the rate of percolation of rainwater and river water through the surface soils cannot be determined. Although the surface has not been graded to promote drainage, very little ponding was noted during the RI. Visual evidence suggests that the landfill cover does not appear to be capped with soils that would inhibit infiltration of surface waters.

Generally, the thicker the fill, the more concentrated the leachate will become. Quality of the leachate is a function of the composition, degree of compaction,

Figure 9E
Description of Landfill Sections
Lee's Lane Landfill

Attachment B


Photographs



Photograph 1 - Entrance Gate at Lee's Lane



Photograph 2 - View Looking North Along the Levee from the Lee's Lane Crossing
Note Gas Collection Wells at Left



Photograph 3 - Top of Gas Collection Well #28 Under Water Ponded in the Ditch Parallel to the Line of Gas Collection Wells



Photograph 4 - Blower House and Gas Collection Wells from Lee's Lane



Photograph 5A - View Looking South Along the Levee from the Lee's Lane Crossing
Note Asphalt Walkout Along Top of Levee



Photograph 5B - View Looking South Along the Levee from the Lee's Lane Crossing



Photograph 6 - Approach to Landfill Along Lee's Lane




Photograph 7 - Central Track Wooded, Hummocky Area




Photograph 8 - Rock Lined Ditch at North End of Central Tract and Wooded North Tract




Photograph 9 - Rip-Rap Bank Protection



Photograph 10A - Settlement Monuments




Photograph 10B - Settlement Monuments



Photograph 11 - Ruts Along Clay Cap




Photograph 12 - Blocked Shale-Lined Drainage Ditch Across Clay Cap at the Top of the Rip-Rapped Slope




Photograph 13A - Sediment Build-up At Drainage Pipe and Ponded Water Upstream of Drainage Pipe Blockage



Photograph 13B - Sediment Build-up At Drainage Pipe and Ponded Water Upstream of Drainage Pipe Blockage



Photograph 14 - Access Road in South Tract




Photograph 15A - Debris and Hummocky Surface in South Tract




Photograph 15B - Debris and Hummocky Surface in South Tract



Photograph 16 - Ruts and Eroded Surface Due to Quad Runner Traffic; View from Putnam Road Looking South




Photograph 17 - Piping at the Subsurface Gas Collection Blower House



Photograph 18 - Barrier Across Putnam Road




Photograph 19A - Water Meter and Fireplug Along Putnam Road




Photograph 19B - Water Meter and Fireplug Along Putnam Road



Photograph 20A – Elastic Material Observed at Surface



Photograph 20B – Elastic Material Observed at Surface



Photograph 21 – Buried Drum with Elastic Material

Attachment C

Forms

LET'S LAND LANDFILL
LOUISVILLE, KY
3RD 5-YEAR REVIEW

February 25, 2003

NAME	AGENCY	TELEPHONE NUMBER	E-MAIL ADDRESS
JOHN JEWETT	COOPER ENGINEERS	502-325-6393	john.jewett@cooper-engineers.com
AL SCALZO	"	502-325-6329	alscalzo@cooper-engineers.com
JOE LITTON	"	502-325-6333	joe.litton@cooper-engineers.com
"	again	502-325-6333	joel.litton@cooper-engineers.com
ROBERT L. LITTON	MS&S	502-325-6329	robert.litton@cooper-engineers.com
FRANK A. KINZLE	US EPA	404 562 5809	frank.kinzle@epa.gov

Form C-1
5-Year Review Site
Inspection Attendees

REPORT OF FIELD OBSERVATION LEE'S LANE LANDFILL SITE, LOUISVILLE, KENTUCKY

Observation Report No: FY-03-3Q Date of Observation 02/25/03
 Time Arrived Onsite: 11:20 AM Time Departed Site: 12:30 PM
 Field Personnel: MICHAEL HAGAN, UW III; RICHARD H WATKINS, SR SPECIAL
ASST. TO DIR., JOHN JENT, U.S. ARMY COE, NAT PETERS, U.S. ARMY COE, M.
FEMI AKINDELE, U.S. EPA, KEN LOGSDON KY, ENVIRONMENTAL PROTECTION CAB,

Section A: General Site Conditions

Observations:	<u>Yes*</u>	<u>No</u>	<u>Not Observed</u>	<u>Comment No.</u>
1. Major settlement of topsoil or erosion exposing waste/fill material	—	<u>XX</u>	—	—
2. Evidence of leachate seepage	—	<u>XX</u>	—	—
3. Distressed Vegetation	—	<u>XX</u>	—	—
4. Pot holes, erosion of access road	—	<u>XX</u>	—	<u>A-4</u>

Section B: Institutional Controls

Observations:	<u>Yes*</u>	<u>No</u>	<u>Not Observed</u>	<u>Comment No.</u>
1. Structural problem with Lee's Lane gate or barricade	—	<u>XX</u>	—	<u>B-1</u>
2. Structural problem with Putman Ave. barricade	—	<u>XX</u>	—	<u>B-2</u>
3. Lee's Lane gate unlocked	—	<u>XX</u>	—	—
4. Broken or missing lock	—	<u>XX</u>	—	—

Section C: Gas Collection System

Observations:	<u>Yes*</u>	<u>No</u>	<u>Not Observed</u>	<u>Comme No.</u>
1. Vandalism to blower house walls, or moisture traps	—	<u>XX</u>	—	—
2. Structural damage to blower house	—	—	—	—
3. Blower not operating or visible damage	—	—	—	—
4. Blower house not secure and unclean	—	—	—	—

Form C-2
5-Year Review Site Inspection Checklist
(from MSD)

Review Site Inspection Checklist

(SD)

Observations:	<u>Yes*</u>	<u>No</u>	<u>Not Observed</u>	<u>Comment No.</u>
5. Service box lids not in place	—	<u>XX</u>	—	—
6. Alarm and blower controls not functioning	—	<u>XX</u>	—	—
7. Settlement or tilting of well/moisture trap concrete collars	<u>XX</u>	—	—	<u>C-7</u>
8. Well/moisture trap covers missing or damaged	<u>XX</u>	—	—	<u>C-8</u>
9. Excessive vegetation covering wells/moisture traps	—	<u>XX</u>	—	—
10. Adjustment valve inaccessible	—	<u>XX</u>	—	—
11. Well/moisture trap caps, plugs, and piping missing	—	<u>XX</u>	—	—
12. Blower house and well/moisture trap signs missing or damaged	—	<u>XX</u>	—	—

Section D: Groundwater & Gas Monitor Wells

Observations:	<u>Yes*</u>	<u>No</u>	<u>Not Observed</u>	<u>Comment No.</u>
1. Wells unlocked	—	<u>XX</u>	—	—
2. Guard posts and rails missing or damaged	—	<u>XX</u>	—	—
3. Protective casing missing, damaged or rusted	<u>XX</u>	—	—	<u>D-3</u>
4. Concrete pads damaged or cracked	—	<u>XX</u>	—	—
5. Possible surface water infiltration into wells	—	<u>XX</u>	—	—
6. Excessive vegetation or debris around wells	—	<u>XX</u>	—	—
7. Well cap missing or damaged	—	<u>XX</u>	—	—
8. Tubing, fittings, and valves missing or damaged (gas wells only)	—	—	<u>XX</u>	<u>D-8</u>

Section E: Bank Protection Controls

Observations:	<u>Yes*</u>	<u>No</u>	<u>Not Observed</u>	<u>Comment No.</u>
1. Subsidence of slope, sloughing or caving	—	<u>XX</u>	—	—
2. Erosion of rip-rap or underlying material	—	<u>XX</u>	—	—
3. Abnormally damp areas, wet ground vegetation	—	<u>XX</u>	—	—
4. Soft spots in surface	—	<u>XX</u>	—	—
5. Seepage, water flow, piping, or sand boils	—	<u>XX</u>	—	—
6. Undermining of rip-rap	—	<u>XX</u>	—	—
7. Vegetative growth on rip-rap slope	<u>XX</u>	—	—	<u>E-7</u>
8. Buildup of trash and debris on rip-rap	—	<u>XX</u>	—	<u>E-8</u>
9. Exposed trash or filter fabric	—	<u>XX</u>	—	—
10. Tilting trees	—	<u>XX</u>	—	—
11. Tension cracks	—	<u>XX</u>	—	—
12. Survey monuments missing or damaged	—	<u>XX</u>	—	—

Section F: Surface Waste Cleanup/Cover

Observations:	<u>Yes*</u>	<u>No</u>	<u>Not Observed</u>	<u>Comment No.</u>
1. Swales greater than 1 foot wide and 2 inches deep	—	<u>XX</u>	—	—
2. Cracks greater than 1 inch wide and 6 inches deep	—	<u>XX</u>	—	—
3. Areas of erosional damage to grass	<u>XX</u>	—	—	<u>F-3</u>
4. Inadequate grass cover (area > 36 ft ²)	<u>XX</u>	—	—	<u>F-4</u>
5. Ponded water (area larger than 2 feet in diameter and 3 inches deep)	<u>XX</u>	—	—	<u>F-5</u>
6. Erosion or ponded water greater than 12 inches deep (requires immediate repair)	—	<u>XX</u>	—	—

*If yes, assign a comment no. in the last column and follow instructions on comment sheet.

REPORT OF FIELD OBSERVATION
LEE'S LANE LANDFILL SITE, LOUISVILLE, KENTUCKY

Observation Report No: FY-03-2Q Date of Observation 12/17/02

Site Map

Observer's Signature: _____
Date: _____

0
REPORT OF FIELD OBSERVATION
LEE'S LANE LANDFILL SITE, LOUISVILLE, KENTUCKY

Observation Report No.: FY03-3Q

Date of Observation: 02/25/03

Instruction: If any item is checked yes, provide details of the problem and maintenance recommendations below and indicate the location of deficiency on the site map provided.

Comment No.:

Comment

- | | |
|-----|--|
| A-4 | Small amount of rutting was observed on the gravel road leading to gas collection Well No. 5 from ATVs. |
| B-1 | Condition of the Lee's Lane barricade remains unchanged from previous quarterly institutional inspections. |
| B-2 | Condition of the Putnam Avenue barricade remains unchanged from previous quarterly institutional inspections. Intrusions into the landfill site and flood protection levee areas by ATVs from the woods adjacent to the Putnam Avenue barricade has been reduced, but is still evident. The landfill site and flood protection levee continues to receive surveillance by the Jefferson County Police. |

Comment No.

Corrective Action Performed

- | | |
|-----|--|
| A-4 | Schedule gravelling of the access road leading to Well No. 5 to fill rutted areas during FY03-4Q as weather and scheduling permit. |
| B-1 | Continue to observe condition of the Lee's Lane barricade during future quarterly institutional inspections. Schedule painting of Lee's Lane barricade during FY03-4Q. |

B-2 Continue to observe condition of the Putnam Avenue barricade during future quarterly institutional inspections. Replace damaged "No Trespass – Keep Out" signs at strategic locations along the access roads and Mill Creek cut-off channel areas in an effort to discourage ATV intrusions and trespass into the landfill and levee area sites. Schedule painting of Putnam barricade by end of FY03-4Q.

<u>Comment No.:</u>	<u>Comment</u>
---------------------	----------------

C-7	Observed tilted well and moisture trap concrete collars for 2, 4, 8, 11, 12, 14, and 16
-----	---

C-8	Observed covers missing for moisture traps 25, 26, and 27.
-----	--

D-3	Observed protective casing of gas monitoring wells rusting.
-----	---

<u>Comment No.</u>	<u>Corrective Action Performed</u>
--------------------	------------------------------------

C-7	Schedule resetting of tilted well and moisture trap concrete collars for moisture traps 2, 4, 8, 11, 12, 14 and 16 weather and scheduling permitting.
-----	---

C-8	Obtain replacement covers and install on moisture traps
-----	---

D-3	Schedule painting of gas monitoring wells protective casings during FY03-4Q.
-----	--

Comment No.:

Comment

- D-8 Monitoring wells tubing, fittings, and valves were not directly observed but no external damage or disturbance to enclosures was evident.
- E-7 Observed vegetative growth on portions of the riprap levee and riprap drainage channel slopes.
- E-8 Observed small amount of trash and debris build-up on the riprap area from prior observations. Trespassers continue to utilize the debris as fuel for small bonfires, thereby eliminating the necessity to remove the debris from the riprap area. Also observed automobile hood that has been dumped in scale.
- F-3 Observed areas erosional damage to grass caused by off road vehicles
- F-4 Observed areas of inadequate grass cover from intrusion of ATVs.
- F-5 Observed area of ponding water from intrusion of off road vehicles creating several ruts and low areas.

Comment No.

Corrective Action Performed

- D-8 Monitoring well tubing, fittings, and valves were not directly observed but no external damage or disturbance to enclosures was evident.
- E-7 Spraying of the riprap drainage channels and riprap cap area should be scheduled during FY03-4Q.
- E-8 Schedule removal of large debris and automobile hood and monitor for additional debris.
- F-3 Monitor and schedule restoration of eroded areas as required as weather and staffing permit.
- F-4 Monitored at future quarterly institutional inspections backfill and seed areas as necessary.
- F-5 Condition of ruts left by ATVs and other vehicles should be monitored at future quarterly institutional inspections and scheduled backfilling as necessary. Also schedule redevelopment of drainage swales as needed during FY03-4Q as weather and staffing permit.

25071454

[illegible]

MD = Composite MD effect size

KEYWORDS:

Parameter (Symbol)	Reference Configuration										Sensitivity Analysis									
	Value	Unit	Min	Max	Standard Deviation	25th Percentile	50th Percentile	75th Percentile	90th Percentile	95th Percentile	Value	Unit	Min	Max	Standard Deviation	25th Percentile	50th Percentile	75th Percentile	90th Percentile	95th Percentile
Parameter A (mm)	1.2	mm	1.0	1.4	0.1	1.1	1.2	1.3	1.4	1.5	1.2	mm	1.0	1.4	0.1	1.1	1.2	1.3	1.4	1.5
	0.5	mm	0.4	0.6	0.05	0.45	0.5	0.55	0.6	0.65	0.5	mm	0.4	0.6	0.05	0.45	0.5	0.55	0.6	0.65
Parameter B (mm)	0.1	mm	0.05	0.15	0.02	0.08	0.1	0.12	0.14	0.16	0.1	mm	0.05	0.15	0.02	0.08	0.1	0.12	0.14	0.16
	0.05	mm	0.02	0.08	0.01	0.03	0.04	0.05	0.06	0.07	0.05	mm	0.02	0.08	0.01	0.03	0.04	0.05	0.06	0.07
Parameter C (mm)	0.02	mm	0.01	0.03	0.005	0.01	0.015	0.02	0.025	0.03	0.02	mm	0.01	0.03	0.005	0.01	0.015	0.02	0.025	0.03
	0.01	mm	0.005	0.015	0.002	0.005	0.008	0.01	0.012	0.015	0.01	mm	0.005	0.015	0.002	0.005	0.008	0.01	0.012	0.015
Parameter D (mm)	0.005	mm	0.002	0.008	0.001	0.003	0.004	0.005	0.006	0.007	0.005	mm	0.002	0.008	0.001	0.003	0.004	0.005	0.006	0.007
	0.002	mm	0.001	0.003	0.0005	0.001	0.0015	0.002	0.0025	0.003	0.002	mm	0.001	0.003	0.0005	0.001	0.0015	0.002	0.0025	0.003
Parameter E (mm)	0.001	mm	0.0005	0.0015	0.0002	0.0005	0.0008	0.001	0.0012	0.0015	0.001	mm	0.0005	0.0015	0.0002	0.0005	0.0008	0.001	0.0012	0.0015
	0.0005	mm	0.0002	0.0008	0.0001	0.0002	0.0003	0.0004	0.0005	0.0006	0.0005	mm	0.0002	0.0008	0.0001	0.0002	0.0003	0.0004	0.0005	0.0006
Parameter F (mm)	0.0002	mm	0.0001	0.0003	0.00005	0.0001	0.00015	0.0002	0.00025	0.0003	0.0002	mm	0.0001	0.0003	0.00005	0.0001	0.00015	0.0002	0.00025	0.0003
	0.0001	mm	0.00005	0.00015	0.00002	0.00005	0.00008	0.0001	0.00012	0.00015	0.0001	mm	0.00005	0.00015	0.00002	0.00005	0.00008	0.0001	0.00012	0.00015
Parameter G (mm)	0.00005	mm	0.00002	0.00008	0.00001	0.00002	0.00003	0.00004	0.00005	0.00006	0.00005	mm	0.00002	0.00008	0.00001	0.00002	0.00003	0.00004	0.00005	0.00006
	0.00002	mm	0.00001	0.00003	0.000005	0.00001	0.000015	0.00002	0.000025	0.00003	0.00002	mm	0.00001	0.00003	0.000005	0.00001	0.000015	0.00002	0.000025	0.00003
Parameter H (mm)	0.00001	mm	0.000005	0.000015	0.000002	0.000005	0.000008	0.00001	0.000012	0.000015	0.00001	mm	0.000005	0.000015	0.000002	0.000005	0.000008	0.00001	0.000012	0.000015
	0.000005	mm	0.000002	0.000008	0.000001	0.000002	0.000003	0.000004	0.000005	0.000006	0.000005	mm	0.000002	0.000008	0.000001	0.000002	0.000003	0.000004	0.000005	0.000006
Parameter I (mm)	0.000002	mm	0.000001	0.000003	0.0000005	0.000001	0.0000015	0.000002	0.0000025	0.000003	0.000002	mm	0.000001	0.000003	0.0000005	0.000001	0.0000015	0.000002	0.0000025	0.000003
	0.000001	mm	0.0000005	0.0000015	0.0000002	0.0000005	0.0000008	0.000001	0.0000012	0.0000015	0.000001	mm	0.0000005	0.0000015	0.0000002	0.0000005	0.0000008	0.000001	0.0000012	0.0000015
Parameter J (mm)	0.0000005	mm	0.0000002	0.0000008	0.0000001	0.0000002	0.0000003	0.0000004	0.0000005	0.0000006	0.0000005	mm	0.0000002	0.0000008	0.0000001	0.0000002	0.0000003	0.0000004	0.0000005	0.0000006
	0.0000002	mm	0.0000001	0.0000003	0.00000005	0.0000001	0.00000015	0.0000002	0.00000025	0.0000003	0.0000002	mm	0.0000001	0.0000003	0.00000005	0.0000001	0.00000015	0.0000002	0.00000025	0.0000003
Parameter K (mm)	0.0000001	mm	0.00000005	0.00000015	0.00000002	0.00000005	0.00000008	0.0000001	0.00000012	0.00000015	0.0000001	mm	0.00000005	0.00000015	0.00000002	0.00000005	0.00000008	0.0000001	0.00000012	0.00000015
	0.00000005	mm	0.00000002	0.00000008	0.00000001	0.00000002	0.00000003	0.00000004	0.00000005	0.00000006	0.00000005	mm	0.00000002	0.00000008	0.00000001	0.00000002	0.00000003	0.00000004	0.00000005	0.00000006
Parameter L (mm)	0.00000002	mm	0.00000001	0.00000003	0.000000005	0.00000001	0.000000015	0.00000002	0.000000025	0.00000003	0.00000002	mm	0.00000001	0.00000003	0.000000005	0.00000001	0.000000015	0.00000002	0.000000025	0.00000003
	0.00000001	mm	0.000000005	0.000000015	0.000000002	0.000000005	0.000000008	0.00000001	0.000000012	0.000000015	0.00000001	mm	0.000000005	0.000000015	0.000000002	0.000000005	0.000000008	0.00000001	0.000000012	0.000000015
Parameter M (mm)	0.000000005	mm	0.000000002	0.000000008	0.000000001	0.000000002	0.000000003	0.000000004	0.000000005	0.000000006	0.000000005	mm	0.000000002	0.000000008	0.000000001	0.000000002	0.000000003	0.000000004	0.000000005	0.000000006
	0.000000002	mm	0.000000001	0.000000003	0.0000000005	0.000000001	0.0000000015	0.000000002	0.0000000025	0.000000003	0.000000002	mm	0.000000001	0.000000003	0.0000000005	0.000000001	0.0000000015	0.000000002	0.0000000025	0.000000003
Parameter N (mm)	0.000000001	mm	0.0000000005	0.0000000015	0.0000000002	0.0000000005	0.0000000008	0.000000001	0.0000000012	0.0000000015	0.000000001	mm	0.0000000005	0.0000000015	0.0000000002	0.0000000005	0.0000000008	0.000000001	0.0000000012	0.0000000015
	0.0000000005	mm	0.0000000002	0.0000000008	0.0000000001	0.0000000002	0.0000000003	0.0000000004	0.0000000005	0.0000000006	0.0000000005	mm	0.0000000002	0.0000000008	0.0000000001	0.0000000002	0.0000000003	0.0000000004	0.0000000005	0.0000000006
Parameter O (mm)	0.0000000002	mm	0.0000000001	0.0000000003	0.00000000005	0.0000000001	0.00000000015	0.0000000002	0.00000000025	0.0000000003	0.0000000002	mm	0.0000000001	0.0000000003	0.00000000005	0.0000000001	0.00000000015	0.0000000002	0.00000000025	0.0000000003
	0.0000000001	mm	0.00000000005	0.00000000015	0.00000000002	0.00000000005	0.00000000008	0.0000000001	0.00000000012	0.00000000015	0.0000000001	mm	0.00000000005	0.00000000015	0.00000000002	0.00000000005	0.00000000008	0.0000000001	0.00000000012	0.00000000015
Parameter P (mm)	0.00000000005	mm	0.00000000002	0.00000000008	0.00000000001	0.00000000002	0.00000000003	0.00000000004	0.00000000005	0.00000000006	0.00000000005	mm	0.00000000002	0.00000000008	0.00000000001	0.00000000002	0.00000000003	0.00000000004	0.00000000005	0.00000000006
	0.00000000002	mm	0.00000000001	0.00000000003	0.000000000005	0.00000000001	0.000000000015	0.00000000002	0.000000000025	0.00000000003	0.00000000002	mm	0.00000000001	0.00000000003	0.000000000005	0.00000000001	0.000000000015	0.00000000002	0.000000000025	0.00000000003
Parameter Q (mm)	0.00000000001	mm	0.000000000005	0.000000000015	0.000000000002	0.000000000005	0.000000000008	0.00000000001	0.000000000012	0.000000000015	0.00000000001	mm	0.000000000005	0.000000000015	0.000000000002	0.000000000005	0.000000000008	0.00000000001	0.000000000012	0.000000000015
	0.000000000005	mm	0.000000000002	0.000000000008	0.000000000001	0.000000000002	0.000000000003	0.000000000004	0.000000000005	0.000000000006	0.000000000005	mm	0.000000000002	0.000000000008	0.000000000001	0.000000000002	0.000000000003	0.000000000004	0.000000000005	0.000000000006
Parameter R (mm)	0.000000000002	mm	0.000000000001	0.000000000003	0.0000000000005	0.000000000001	0.0000000000015	0.000000000002	0.0000000000025	0.000000000003	0.000000000002	mm	0.000000000001	0.000000000003	0.0000000000005	0.000000000001	0.0000000000015	0.000000000002	0.0000000000025	0.000000000003
	0.000000000001	mm	0.0000000000005	0.0000000000015	0.0000000000002	0.0000000000005	0.0000000000008	0.000000000001	0.0000000000012	0.0000000000015	0.000000000001	mm	0.0000000000005	0.0000000000015	0.0000000000002	0.0000000000005	0.0000000000008	0.000000000001	0.0000000000012	0.0000000000015
Parameter S (mm)	0.0000000000005	mm	0.0000000000002	0.0000000000008	0.0000000000001	0.0000000000002	0.0000000000003	0.0000000000004	0.0000000000005	0.0000000000006	0.0000000000005	mm	0.0000000000002	0.0000000000008	0.0000000000001	0.0000000000002	0.0000000000003	0.0000000000004	0.0000000000005	0.0000000000006
	0.0000000000002	mm	0.0000000000001	0.0000000000003	0.00000000000005	0.0000000000001	0.00000000000015	0.0000000000002	0.00000000000025	0.0000000000003	0.0000000000002	mm	0.0000000000001	0.0000000000003	0.00000000000005	0.0000000000001	0.00000000000015	0.0000000000002	0.00000000000025	0.0000000000003
Parameter T (mm)	0.0000000000001	mm	0.00000000000005	0.00000000000015	0.00000000000002	0.00000000000005	0.00000000000008	0.0000000000001	0.00000000000012	0.00000000000015	0.0000000000001	mm	0.00000000000005	0.00000000000015	0.00000000000002	0.00000000000005	0.00000000000008	0.0000000000001	0.00000000000012	0.00000000000015
	0.00000000000005	mm	0.00000000000002	0.00000000000008	0.00000000000001	0.00000000000002	0.00000000000003	0.00000000000004	0.00000000000005	0.00000000000006	0.00000000000005	mm	0.00000000000002	0.00000000000008	0.00000000000001	0.00000000000002	0.00000000000003	0.00000000000004	0.00000000000005	0.00000000000006
Parameter U (mm)	0.00000000000002	mm	0.00000000000001	0.00000000000003	0.000000000000005	0.00000000000001	0.000000000000015	0.00000000000002	0.000000000000025	0.00000000000003	0.00000000000002	mm	0.00000000000001	0.00000000000003	0.000000000000005	0.00000000000001	0.000000000000015	0.00000000000002	0.000000000000025	0.00000000000003
	0.00000000000001	mm	0.000000000000005	0.000000000000015	0.000000000000002	0.000000000000005	0.000000000000008	0.00000000000001	0.000000000000012	0.000000000000015	0.00000000000001	mm	0.000000000000005	0.000000000000015	0.000000000000002	0.000000000000005	0.000000000000008	0.00000000000001	0.000000000000012	0.000000000000015
Parameter																				

Mg^{2+} is Toxic. Run dryland
 $\text{Mg}^{2+} = \text{Ca} + 2\text{Mg} + \text{Mg}$

SEM/NOTES

Parameter	Baseline Configuration										Optimized Configuration										Summary	
	Model	Size (MB)	Latency (ms)	Throughput (ops/s)	Accuracy (%)	Memory (MB)	Latency (ms)	Throughput (ops/s)	Accuracy (%)	Memory (MB)	Model	Size (MB)	Latency (ms)	Throughput (ops/s)	Accuracy (%)	Memory (MB)	Latency (ms)	Throughput (ops/s)	Accuracy (%)	Memory (MB)		
Model A	1000	100	1000	95.0	100	1000	100	1000	95.0	100	1000	100	1000	95.0	100	1000	100	1000	95.0	100		
	2000	200	2000	96.0	200	2000	200	2000	96.0	200	2000	200	2000	96.0	200	2000	200	2000	96.0	200		
Model B	3000	300	3000	97.0	300	3000	300	3000	97.0	300	3000	300	3000	97.0	300	3000	300	3000	97.0	300		
	4000	400	4000	98.0	400	4000	400	4000	98.0	400	4000	400	4000	98.0	400	4000	400	4000	98.0	400		
Model C	5000	500	5000	99.0	500	5000	500	5000	99.0	500	5000	500	5000	99.0	500	5000	500	5000	99.0	500		
	6000	600	6000	99.5	600	6000	600	6000	99.5	600	6000	600	6000	99.5	600	6000	600	6000	99.5	600		
Model D	7000	700	7000	99.8	700	7000	700	7000	99.8	700	7000	700	7000	99.8	700	7000	700	7000	99.8	700		
	8000	800	8000	99.9	800	8000	800	8000	99.9	800	8000	800	8000	99.9	800	8000	800	8000	99.9	800		
Model E	9000	900	9000	100.0	900	9000	900	9000	100.0	900	9000	900	9000	100.0	900	9000	900	9000	100.0	900		
	10000	1000	10000	100.0	1000	10000	1000	10000	100.0	1000	10000	1000	10000	100.0	1000	10000	1000	10000	100.0	1000		

NO - Compound not detected

OFFENSE AND

[illegible]

41 = maximum (uncompressed) length (bytes)

•

[illegible]

Form C-4 Gas Monitoring Wells

[illegible]

Case		First 1000 Cases										Second 1000 Cases									
		7000-7200	7200-7400	7400-7600	7600-7800	7800-8000	8000-8200	8200-8400	8400-8600	8600-8800	8800-9000	9000-9200	9200-9400	9400-9600	9600-9800	9800-10000	10000-10200	10200-10400	10400-10600	10600-10800	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-2100	2100-2200	2200-2300	2300-2400	2400-2500	2500-2600	2600-2700	2700-2800	2800-2900	2900-3000	
Length (m)	2700-2800	2800-2900	2900-3000	3000-3100	3100-3200	3200-3300	3300-3400	3400-3500	3500-3600	3600-3700	3700-3800	3800-3900	3900-4000	4000-4100	4100-4200	4200-4300	4300-4400	4400-4500	4500-4600	4600-4700	
Weight (kg)	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500</																

E-X		Semi-Ins. Type										Conduct. Type																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																						
25% E.C.I. (%)	25% E.C.I. (imp/ft)	1.64E	2.21E	2.78E	3.35E	3.92E	4.49E	5.06E	5.63E	6.20E	6.77E	7.34E	7.91E	8.48E	9.05E	9.62E	10.19E	10.76E	11.33E	11.90E	12.47E	13.04E	13.61E	14.18E	14.75E	15.32E	15.89E	16.46E	17.03E	17.60E	18.17E	18.74E	19.31E	19.88E	20.45E	21.02E	21.59E	22.16E	22.73E	23.30E	23.87E	24.44E	25.01E	25.58E	26.15E	26.72E	27.29E	27.86E	28.43E	29.00E	29.57E	30.14E	30.71E	31.28E	31.85E	32.42E	32.99E	33.56E	34.13E	34.70E	35.27E	35.84E	36.41E	36.98E	37.55E	38.12E	38.69E	39.26E	39.83E	40.40E	40.97E	41.54E	42.11E	42.68E	43.25E	43.82E	44.39E	44.96E	45.53E	46.10E	46.67E	47.24E	47.81E	48.38E	48.95E	49.52E	50.09E	50.66E	51.23E	51.80E	52.37E	52.94E	53.51E	54.08E	54.65E	55.22E	55.79E	56.36E	56.93E	57.50E	58.07E	58.64E	59.21E	59.78E	60.35E	60.92E	61.49E	62.06E	62.63E	63.20E	63.77E	64.34E	64.91E	65.48E	66.05E	66.62E	67.19E	67.76E	68.33E	68.90E	69.47E	70.04E	70.61E	71.18E	71.75E	72.32E	72.89E	73.46E	74.03E	74.60E	75.17E	75.74E	76.31E	76.88E	77.45E	78.02E	78.59E	79.16E	79.73E	80.30E	80.87E	81.44E	82.01E	82.58E	83.15E	83.72E	84.29E	84.86E	85.43E	86.00E	86.57E	87.14E	87.71E	88.28E	88.85E	89.42E	89.99E	90.56E	91.13E	91.70E	92.27E	92.84E	93.41E	93.98E	94.55E	95.12E	95.69E	96.26E	96.83E	97.40E	97.97E	98.54E	99.11E	99.68E	100.25E	100.82E	101.39E	101.96E	102.53E	103.10E	103.67E	104.24E	104.81E	105.38E	105.95E	106.52E	107.09E	107.66E	108.23E	108.80E	109.37E	109.94E	110.51E	111.08E	111.65E	112.22E	112.79E	113.36E	113.93E	114.50E	115.07E	115.64E	116.21E	116.78E	117.35E	117.92E	118.49E	119.06E	119.63E	120.20E	120.77E	121.34E	121.91E	122.48E	123.05E	123.62E	124.19E	124.76E	125.33E	125.90E	126.47E	127.04E	127.61E	128.18E	128.75E	129.32E	129.89E	130.46E	131.03E	131.60E	132.17E	132.74E	133.31E	133.88E	134.45E	135.02E	135.59E	136.16E	136.73E	137.30E	137.87E	138.44E	139.01E	139.58E	140.15E	140.72E	141.29E	141.86E	142.43E	143.00E	143.57E	144.14E	144.71E	145.28E	145.85E	146.42E	146.99E	147.56E	148.13E	148.70E	149.27E	149.84E	150.41E	150.98E	151.55E	152.12E	152.69E	153.26E	153.83E	154.40E	154.97E	155.54E	156.11E	156.68E	157.25E	157.82E	158.39E	158.96E	159.53E	160.10E	160.67E	161.24E	161.81E	162.38E	162.95E	163.52E	164.09E	164.66E	165.23E	165.80E	166.37E	166.94E	167.51E	168.08E	168.65E	169.22E	169.79E	170.36E	170.93E	171.50E	172.07E	172.64E	173.21E	173.78E	174.35E	174.92E	175.49E	176.06E	176.63E	177.20E	177.77E	178.34E	178.91E	179.48E	180.05E	180.62E	181.19E	181.76E	182.33E	182.90E	183.47E	184.04E	184.61E	185.18E	185.75E	186.32E	186.89E	187.46E	188.03E	188.60E	189.17E	189.74E	190.31E	190.88E	191.45E	192.02E	192.59E	193.16E	193.73E	194.30E	194.87E	195.44E	196.01E	196.58E	197.15E	197.72E	198.29E	198.86E	199.43E	199.99E	200.56E	201.13E	201.70E	202.27E	202.84E	203.41E	203.98E	204.55E	205.12E	205.69E	206.26E	206.83E	207.40E	207.97E	208.54E	209.11E	209.68E	210.25E	210.82E	211.39E	211.96E	212.53E	213.10E	213.67E	214.24E	214.81E	215.38E	215.95E	216.52E	217.09E	217.66E	218.23E	218.80E	219.37E	219.94E	220.51E	221.08E	221.65E	222.22E	222.79E	223.36E	223.93E	224.50E	225.07E	225.64E	226.21E	226.78E	227.35E	227.92E	228.49E	229.06E	229.63E	230.20E	230.77E	231.34E	231.91E	232.48E	233.05E	233.62E	234.19E	234.76E	235.33E	235.90E	236.47E	237.04E	237.61E	238.18E	238.75E	239.32E	239.89E	240.46E	241.03E	241.60E	242.17E	242.74E	243.31E	243.88E	244.45E	245.02E	245.59E	246.16E	246.73E	247.30E	247.87E	248.44E	249.01E	249.58E	250.15E	250.72E	251.29E	251.86E	252.43E	253.00E	253.57E	254.14E	254.71E	255.28E	255.85E	256.42E	256.99E	257.56E	258.13E	258.70E	259.27E	259.84E	260.41E	260.98E	261.55E	262.12E	262.69E	263.26E	263.83E	264.40E	264.97E	265.54E	266.11E	266.68E	267.25E	267.82E	268.39E	268.96E	269.53E	270.10E	270.67E	271.24E	271.81E	272.38E	272.95E	273.52E	274.09E	274.66E	275.23E	275.80E	276.37E	276.94E	277.51E	278.08E	278.65E	279.22E	279.79E	280.36E	280.93E	281.50E	282.07E	282.64E	283.21E	283.78E	284.35E	284.92E	285.49E	286.06E	286.63E	287.20E	287.77E	288.34E	288.91E	289.48E	290.05E	290.62E	291.19E	291.76E	292.33E	292.90E	293.47E	294.04E	294.61E	295.18E	295.75E	296.32E	296.89E	297.46E	298.03E	298.60E	299.17E	299.74E	300.31E	300.88E	301.45E	302.02E	302.59E	303.16E	303.73E	304.30E	304.87E	305.44E	306.01E	306.58E	307.15E	307.72E	308.29E	308.86E	309.43E	309.99E	310.56E	311.13E	311.70E	312.27E	312.84E	313.41E	313.98E	314.55E	315.12E	315.69E	316.26E	316.83E	317.40E	317.97E	318.54E	319.11E	319.68E	320.25E	320.82E	321.39E	321.96E	322.53E	323.10E	323.67E	324.24E	324.81E	325.38E	325.95E	326.52E	327.09E	327.66E	328.23E	328.80E	329.37E	329.94E	330.51E	331.08E	331.65E	332.22E	332.79E	333.36E	333.93E	334.50E	335.07E	335.64E	336.21E	336.78E	337.35E	337.92E	338.49E	339.06E	339.63E	340.20E	340.77E	341.34E	341.91E	342.48E	343.05E	343.62E	344.19E	344.76E	345.33E	345.90E	346.47E	347.04E	347.61E	348.18E	348.75E	349.32E	349.89E	350.46E	351.03E	351.60E	352.17E	352.74E	353.31E	353.88E	354.45E	355.02E	355.59E	356.16E	356.73E	357.30E	357.87E	358.44E	359.01E	359.58E	360.15E	360.72E	361.29E	361.86E	362.43E	363.00E	363.57E	364.14E	364.71E	365.28E	365.85E	366.42E	366.99E	367.56E	368.13E	368.70E	369.27E	369.84E	370.41E	370.98E	371.55E	372.12E	372.69E	373.26E	373.83E	374.40E	374.97E	375.54E	376.11E	376.68E	377.25E	377.82E	378.39E	378.96E	379.53E	380.10E	380.67E	381.24E	381.81E	382.38E	382.95E	383.52E	384.09E	384.66E	385.23E	385.80E	386.37E	386.94E	387.51E	388.08E	388.65E	389.22E	389.79E	390.36E	390.93E	391.50E	392.07E	392.64E	393.21E	393.78E	394.35E	394.92E	395.49E	396.06E	396.63E	397.20E	397.77E	398.34E	398.91E	399.48E	400.05E	400.62E	401.19E	401.76E	402.33E	402.90E	403.47E	404.04E	404.61E	405.18E	405.75E	406.32E	406.89E	407.46E	408.03E	408.60E	409.17E	409.74E	410.31E	410.88E	411.45E	412.02E	412.59E	413.16E	413.73E	414.30E	414.87E	415.44E	416.01E	416.58E	417.15E	417.72E	418.29E	418.86E	419.43E	419.99E	420.56E	421.13E	421.70E	422.27E	422.84E	423.41E	423.98E	424.55E	425.12E	425.69E	426.26E	426.83E	427.40E	427.97E	428.54E	429.11E	429.68E	430.25E	430.82E	431.39E	431.96E	432.53E	433.10E	433.67E	434.24E	434.81E	435.38E	435.95E	436.52E	437.09E	437.66E	438.23E	438.80E	439.37E	439.94E	440.51E	441.08E	441.65E	442.22E	442.79E	443.36E	443.93E	444.50E	445.07E	445.64E	446.21E	446.78E	447.35E	447.92E	448.49E	449.06E	449.63E	450.20E	450.77E	451.34E	451.91E	452.48E	453.05E	453.62E	454.19E	454.76E	455.33E	455.90E	456.47E	457.04E	457.61E	458.18E	458.75E	459.32E	459.89E	460.46E	461.03E	461.60E	462.17E	462.74E	463.31E	463.88E	464.45E	465.02E	465.59E	466.16E	466.73E	467.30E	467.87E	468.44E	469.01E	469.58E	470.15E	470.72E	471.29E	471.86E	472.43E	473.00E	473.57E	474.14E	474.71E	475.28E	475.85E	476.42E	476.99E	477.56E	478.13E	478.70E	479.27E	479.84E	480.41E	480.98E	481.55E	482.12E	482.69E	483.26E	483.83E	484.40E	484.97E	485.54E	486.11E	486.68E	487.25E	487.82E	488.39E	488.96E	489.53E	490.10E	490.67E	491.24E	491.81E	492.38E	492.95E	493.52E	494.09E	494.66E	495.23E	495.80E	496.37E	496.94E	497.51E	498.08E	498.65E	499.22E	499.79E	500.36E	500.93E	501.50E	502.07E	502.64E	503.21E	503.78E	504.35E	504.92E	505.49E	506.06E	506.63E	507.20E	507.77E	508.34E	508.91E	509.48E	510.05E	510.62E	511.19E	511.76E	512.33E	512.90E	513.47E	514.04E	514.61E	515.18E	515.75E	516.32E	516.89E	517.46E	518.03E	518.60E	519.17E	519.74E	520.31E	520.88E	521.45E	522.02E	522.59E	523.16E	523.73E	524.30E	524.87E	525.44E	526.01E	526.58E	527.15E	527.72E	528.29E	528.86E	529.43E	529.99E	530.56E	531.13E	531.70E	532.27E	532.84E	533.41E	533.98E	534.55E	535.12E	535.69E	536.26E	536.83E	537.40E	537.97E	538.54E	539.11E	539.68E	540.25E	540.82E	541.39E	541.96E	542.53E	543.10E	543.67E	544.24E	544.81E	545.38E	545.95E	546.52E	547.09E	547.66E	548.23E	548.80E	549.37E	549.94E	550.51E	551.08E	551.65E	552.22E	552.79E	553.36E	553.93E	554.50E	555.07E	555.64E	556.21E	556.78E	557.35E	557.92E	558.49E	559.06E	559.63E	560.20E	560.77E	561.34E	561.91E	562.48E	563.05E	563.62E	564.19E	564.76E	565.33E	565.90E	566.47E	567.04E	567.61E	568.18E	568.75E	569.32E	569.89E	570.46E	571.03E	571.60E	572.17E	572.74E	573.31E	573.88E	574.45E	575.02E	575.59E	576.16E	576.73E	577.30E	577.87E	578.44E	579.01E	579.58E	580.15E	580.72E	581.29E	581.86E	582.43E	583.00E	583.57E	584.14E	584.71E	585.28E	585.85E	586.42E	586.99E	587.56E	588.13E	588.70E	589.27E	589.84E	590.41E	590.98E	591.55E	592.12E	592.69E	593.26E	593.83E	594.40E

[illegible][illegible]

Cells were analyzed by EPR (Caryon, Ltd.) at room temperature using Cary Chromatography/Analysis Spectrometer. Values of "non-detect" were not available.

Appendix A: Summary

[illegible]

Answers for Summary 17

Component	20% LEL [19]	20% UEL [20]	Sampling time															
			11:00 pre-shift	12:00 post-shift	14:00 pre-shift	15:00 post-shift	16:00 pre-shift	17:00 post-shift	18:00 pre-shift	19:00 post-shift	20:00 pre-shift	21:00 post-shift	22:00 pre-shift	23:00 post-shift	24:00 pre-shift	25:00 post-shift	26:00 pre-shift	27:00 post-shift
Benzene	0.335	3.340 (106)	0.36	0.39	0.50	0.54	0.52	0.72	0.71	0.90	0.66	0.74	0.57	0.65	0.53	0.58	0.50	
Toluene	0.3	3.000 (100)	0.17	0.19	0.50	0.87	0.78	1.21	0.95	1.44	0.76	0.94	0.74	1.15	0.74	0.74	0.75	
Xylenes (Total)	0.75	2.760 (100)	0.53	0.70	0.50	1.54	0.68	0.81	0.82	1.09	0.82	0.87	0.82	1.30	0.79	0.76	0.80	
Styrene	1.5	5.000 (100)	0.49	0.59	0.50	0.38	0.52	0.45	0.43	0.52	0.45	0.45	0.45	0.52	0.45	0.45	0.45	
Other Aromatics	0.5	5.000 (100)	0.03	0.05	0.50	0.23	0.10	0.10	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	
Organic Compounds	0.5	5.000 (100)	0.03	0.05	0.50	0.23	0.10	0.10	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	
TD ^a Total (Benzene)	1.25	12.500 (100)	1.00	1.57	1.52	2.32	2.02	3.90	3.41	2.94	2.46	4.51	3.73	3.68	3.40 (100)	3.40 (100)	3.40 (100)	

Medical Air Support Unit

[illegible]

Answers by Subject Area

[illegible]

Answers for Students A:


[illegible]

History of the Vaccine

[illegible]


Form C-7

Methane Measurements



Form C-6

Methane Measurements



Environmental Consultants

2060 Reading Road
Suite 200
Cincinnati, Ohio 45202-1497

513 421-5353
Fax 513 421-2842
info@scsengineers.com

SCS ENGINEERS

March 17, 2003
File No. 9000001.05

U.S. Army Corps of Engineers
CHRL-ED-B
P.O. Box 59
Louisville, Kentucky 40201

Attention: Mr. John Jent

Subject: Condition of Landfill Gas Migration Control System
Lees Lane Landfill, Louisville, Kentucky

Gentlemen:

Thank you for contacting SCS Engineers last Friday, March 14, 2003, to discuss landfill gas related conditions at the Lees Lane Landfill. As you know, a landfill gas (LFG) migration control system was installed at this facility in about 1980. The system consists of approximately 30 vertical extraction wells, installed in the floodwall right-of-way, between the Lees Lane Landfill and the Riverside Gardens Subdivision located adjacent. The gas control system is located in virgin ground outside the refuse limits. Its purpose is to intercept landfill gas that might otherwise be available for migration toward homes located in Riverside Gardens.

When the system was first installed in 1980, landfill gas was found to have migrated up to 1,000 ft outward from the landfill, and into and among the homes of Riverside Gardens. This condition was particularly enhanced under conditions of rising flood waters in the Ohio River, and a rising water table. Under these conditions, landfill gas was apparently "squeezed out" in a smaller, subsurface unsaturated zone. Landfill gas was then found to be migrating to greater distances. An explosion in one of the residential furnaces within Riverside Gardens in about 1977 precipitated an investigation.

Collected landfill gases are of low methane content, and are free vented at a blower/vent facility also located within the floodwall right-of-way. SCS Engineers was the design engineer of record on this original system. I was personally involved at that time with management of the overall project. To date, SCS had performed three separate projects under contract to the Jefferson County Department of Public Works (DPW) at this facility. These included:

1. Investigation of landfill gas migration. This project was performed by SCS Engineers for the Jefferson County DPW beginning in 1978 and ending in 1979. Monitoring probes were installed within the Corps of Engineers floodwall between Lees Lane Landfill and Riverside Gardens. Subsequently, additional monitoring probes were installed throughout Riverside Gardens to determine the extent of landfill gas migration. The first phase of well installations within the floodwall right-of-way were later

Offices Nationwide

Form C-9
Correspondence with SCS
Engineers

Mr. John Sent
March 17, 2003
Page 2

"permanentized" and made part of the ongoing gas monitoring network. Monitoring of the probes out in Riverside Gardens itself was discontinued.

1. SCS was subsequently contracted to the Jefferson County DPW to design and oversee the installation of an LFG migration control system. This project began in 1979, and was completed in late 1980. Actual construction and operational start-up of the migration control system occurred during the summer of 1980. As referenced above, the gas migration control system consisted of approximately 30 extraction wells. Gas was collected in these wells by a blower located inside a blower/vent building. Vacuum was applied to individual wells. Gases were then withdrawn through a subsurface header, and directed back to the blower/vent building.

Immediately after start-up, the gas migration control system was found to be completely effective in mitigating the potential for laterally migrating gases. This was found to be the case both initially under normal conditions, and during subsequent flood stages of the Ohio River. In each case, the gas monitoring network described above was monitored, and readings were generally 0 percent methane, and always below the regulatory limit of 5 percent methane (a.k.a., the lower explosive limit or LEL).

3. SCS was then again contracted in 1985 and 1986. Our client was again the Jefferson County DPW. We were contracted to perform an investigation of the existing gas migration control system, to determine its effectiveness. At that point, the original system had been operational for about 5 years. SCS tested the condition of the entire migration control system, noted operating vacuums and gas compositions, and made recommendations on maintenance needed.

As I recall, our finding at the time was that about 25 percent of the efficiency of the system was gone. Specifically, about one quarter of the wells had broken or silted in, and were no longer effective in controlling laterally-migrating gas. Operating vacuum and flows had considerably diminished, also by at least 25 percent.

This degree of deterioration is typical for LFG migration control systems. Typically, the need for maintenance should be determined on at least an annual basis, and maintenance is likely required at 3-year cycles if the gas collection system is located within a settling and corrosive landfill environment. Alternatively, if the gas system is located in virgin ground (such as is the case here), maintenance at minimum 5-year cycles is likely required.

In our phone conversation the other day, you mentioned that the Metropolitan Sewer District (MSD) of Louisville has assumed ongoing monitoring of the gas monitoring probes, and apparently assumed that responsibility from the Jefferson County DPW at some juncture. Their monitoring has revealed that gas monitoring readings in those probes have been rising over time. A further deterioration of the gas migration control system is now suspected.

Mr. John Lent
March 17, 2003
Page 3

Apparently, the SCS investigation of 1985/1986 was the last observation on the operational effectiveness of the gas control system. If true, one could anticipate that significant deterioration (perhaps total failure) of the LFG collection system is likely at this point. If the system deteriorated 25 percent in the first five years, a much greater deterioration (perhaps to 100 percent) could be expected now. Of course, gas monitoring in the probes is reportedly still below LEL levels. If true, some effectiveness of the gas migration control system must be retained to this date.


In any event, we recommend that a thorough investigation of the operating efficiency of the LFG collection system be performed at the earliest date. The purpose of this program would be to observe operating conditions (well head vacuums, valve settings, physical conditions, and gas compositions). The total flow, vacuum/pressure and gas composition of the blower/vent should also be observed. Down-hole conditions at the extraction wells and any condensate traps should also be examined. The purpose here would be to determine whether wells and traps have physically failed, or silted in over time.

The outcome of this field investigation would be a report summarizing the condition of the system, and making recommendations for improvement. Those recommendations could call for total re-construction of the entire system, if substantial failure of the existing system has already occurred. In short, replacement of the system at that point may be a more productive economic application than attempting to rehabilitate the existing system.

The original work by SCS Engineers on this project was performed by James Walsh and other engineers at our Cincinnati, Ohio location. Most of these personnel remain with the firm. We would be quite interested in serving any client in an investigation of system conditions. We also stand available for maintenance, repair, and even replacement of the LFG system through our subsidiary organization, SCS Field Services. Field Services specializes in the maintenance, replacement, construction, and operation of LFG management systems.

Please contact the undersigned at any time for any further questions you may have, or if you wish to discuss specific work efforts. We appreciate your contacting SCS Engineers.

Sincerely,



James J. Walsh, P.E.
President
SCS ENGINEERS

JW:rae

5-Year Review Questionnaire

Site

City/State

Date:

Phone No.

Name of Citizen

Address

Do you live near the Site? If yes, how long?

Are you familiar with EPA activities over the past years?

What is your overall impression of the project?

Overall, have you been pleased or displeased with cleanup actions at this Site?

What effects, if any, have site operations had on the surrounding community?

Do you still have any concerns regarding EPA clean up activities of the Site?

Do you think you have been kept adequately informed about clean up activities at the Site?

Are you aware of any events, incidents, or activities at the site such as vandalism, trespassing, or emergency responses from local authorities? If so, please give details.

Is there someone else that you would like to recommend we contact for more information?

Do you have any suggestions that EPA can implement to improve

Form C-8A
Telephone Interviews

Interview conducted by:

Date conducted

Form C-8A
Telephone Interviews

5-Year Review Questionnaire

Site

Lois Lane Landfill

City/State

Louisville, Ky

Date:

5/27/03

Phone No.

Name of Citizen

Address

How long have you lived near the Site?

1959

Are you familiar with EPA activities over the past years?

Not really, never got involved.

Do you still have any concerns regarding EPA clean up activities of the Site?

Since not familiar with Site, can't give an answer.

Overall, have you been pleased or displeased with EPA actions at this Site?

Do you think you have been adequately informed about clean up activities at the Site?

Is there any information about the Site that you would like to share with us that would assist in our 5-year review of site activities?

Is there someone else that you would like to recommend we contact for more information?

Do you have any suggestions that EPA can implement to improve communication with the public?

[A copy of the 5-year review will be placed in the Site Information Repository located in the Site Information Repository at _____]

Interview conducted by:

Andrew Bennett

Date conducted:

5-Year Review Questionnaire

Site

City/State

Date:

Phone No.

Name of Citizen

Address

How long have you lived near the Site?

Are you familiar with EPA activities over the past years?

Do you still have any concerns regarding EPA clean up activities of the Site?

Overall, have you been pleased or displeased with EPA actions at this Site?

Do you think you have been adequately informed about clean up activities at the Site?

Is there any information about the Site that you would like to share with us that would assist in our 5-year review of site activities?

Is there anyone else that you would like to recommend we contact for more information?

Do you have any suggestions that EPA can implement to improve communication with the public?

A copy of the 5-year review will be placed in the Site Information Repository file located in the Site Information Repository at

Interview conducted by:

Date conducted:

Forwarded Barbara & State addressed need as a dump - study as in the area.
 of children - to determine contents of the site in group.

N/A

Only since 1996 when she became

involved in the Jack Force

Yes, property next to her used until cleaned up. Contamination?

Yes, property next to her used until cleaned up. Contamination?
 Is there anyone who could help? (Mother and daughter) don't they
 help the community, as people don't trust govt. & waste their help.

Neither - Because neither the State or EPA has been
 very responsive to the community, the people surrounding the
 site have to not trust the govt.

yes - while involved

Many people played in landfill as children. Many of them
 have Jack Force's (a) interest/obsession. What can be done to
 help the people living around the landfill?

Site has been monitored since 1988 in conjunction with Ohio Dept. of Environment. Has their data
 been reviewed?

The Buckle family & Jack Force of Ky Natural Resources

PLA needs to do something to get the community to trust
 what they are saying. Tell - I don't trust the govt.
 Request that a health study be done of people around this site.

By ATSOE

5-Year Review Questionnaire for Govt. Officials

Site

Lee's Lane Landfill

City/State

Louisville, Ky.

Date:

4/28/03

Phone No.

Name

Address

What is your overall impression of the project? The land in area all his life & about a occasion damaged in landfill. In the most part he is pleased with work done there in 1970's, drainage could have been better addressed by attention done today. Landfill would have been handled differently.
 Have there been routine communications or activities conducted by your office regarding the Site? (Site visits, inspections, reporting activities, etc.) If so, please give purpose and results.
There are routine inspections of landfill by MSO of maintenance of area. Due to continued dumping of trash in areas of landfill, this office was in and cleaned up trash etc. & around grass area.

Landfill has been monitored for 15 years.
 Have there been any complaints, violations or other incidents related to the Site requiring a response by your office? If so, please give details of the events and results.

Dumping continued in landfill, mostly by area residents. The landfill is used for 4-wheeling & BMX biking. Trash all over landfill. The landfill is posted & officers arrest trespassers.

Do you feel well informed about the Site's activities and progress? Since direct involvement

in 9/99, yes. He receives reports from industrial waste dept. as monitoring of groundwater and also for methane gas - under control.
 Do you think clean up activities at the Site have had a positive or negative impact on the community? In what ways?
It depends upon where you ask. The community around the landfill is evolving and progressing and improving itself.

Do you have any comments, suggestions, or recommendations regarding the Site's management or operation? yes there are areas in landfill that should be filled in.

The county has excavated dirt from various projects that could be brought in to level the landfill. It has been suggested that the landfill be turned into a recreational area in 5 years.

Interview conducted by Daniel Barnett

Date conducted May 15, 2003

There is question of a mixture of chemical & petroleum compounds reported around landfill area, which are still noticeable. However, the landfill is closed.

3-Year Review Questionnaire for Govt. Officials

Quantity of 100
Civic Center
Miles 50

Site

City/State

Date:

Phone No.

Name

Address

What is your overall impression of the project?

Overall looks good - looks
like area of open (wetland) ponds sweeping up - looking
control to access - doesn't appear to be a lot of surface problem.
if more risk at site, would want more control to be made.
Have there been routine communications or activities conducted by your office regarding the Site?
(Site visits, inspections, reporting activities, etc.) If so, please give purpose and results.
Yes they discuss quarterly report prepared by MSA. Once a
month / year their office people go to site.

Have there been any complaints, violations or other incidents related to the Site requiring a response by your office? If so, please give details of the events and results.

Not that I know of.

Do you feel well informed about the Site's activities and progress?

Quite well informed.
Keeping generally up to date.

Do you think clean up activities at the Site have had a positive or negative impact on the community? In what ways?

Keeping homes from blowing up - in some days real problem

Do you have any comments, suggestions, or recommendations regarding the Site's management or operation?

* well that are suppose to extract wetland, why were they
designed as they were? might need to be updated
need regular pattern of next week - need to investigate current
Interview conducted by Diana B. Smith does not address
some areas.

Date conducted

5-Year Review Questionnaire for GOVT. Officials

Site

Levee Lake Landfill

City/State

Louisville, Ky

Date:

4/28/03

Phone No.

Name

Address

What is your overall impression of the project?

Overall landfill is generally intact & stable. However, there are several areas that are in question. Pip-rap leaks along river. Locals have been dumping in landfill since open top.

Have there been routine communications or activities conducted by your office regarding the Site? (Site visits, inspections, reporting activities, etc.) If so, please give purpose and results.

Nothing routinely done over past 10 years. They did go out to site a week or two ago. Will be taking GPS of areas in landfill. Monitoring is being done by MSD of methane gas from landfill.

Have there been any complaints, violations or other incidents related to the Site requiring a response by your office? If so, please give details of the events and results.

Not recently - several years ago residents complained about barrels being dumped in landfill. The barrels began bubbling up through surface as a river in center of landfill toward S. approx 3 years ago - knew still there some saturation. Birds involved.

Do you feel well informed about the Site's activities and progress?

Do you think clean up activities at the Site have had a positive or negative impact on the community? In what ways?

was back in 1970's - if done today it would be a better cleanup action

Do you have any comments, suggestions, or recommendations regarding the Site's management or operation?

Landfill is situated in a corner of landfill and has its looks

Interview conducted by

Diane Barrett

Date conducted

4/28/03

* paths are apparent throughout landfill either made by wild life or people - glimmers of metal can be seen along paths.

chemical plants in the immediate area, would be difficult to attribute odors as being from only the landfill.

5-Year Review Questionnaire

Site Lee's Lane Landfill
City/State Louisville, Ky.

Date: 3/25/03 Phone No. _____

Name of Citizen _____

Address _____

How long have you lived near the Site? N/A

Are you familiar with EPA activities over the past years? Yes Regularly

Do you still have any concerns regarding EPA clean up activities of the Site?
Not real strong current. ~~Concern~~ public concern

Overall, have you been pleased or displeased with EPA actions at this Site?
Pleased

Do you think you have been adequately informed about clean up activities at the Site?
Like so

Is there any information about the Site that you would like to share with us that would assist in our 5-year review of site activities?
Health Dept. no longer monitors the Site

Is there someone else that you would like to recommend we contact for more information?
Donna Bolen w/ West County Jail (area) 502-4667

Do you have any suggestions that EPA can implement to improve communication with the public?

(A copy of the 5-year review will be placed in the Site Information Repository (SIR) located in the Site Information Repository at _____)

Interview conducted by Alice Bouch
Date conducted: 3/25/03

5-Year Review Questionnaire

Site Lee's Lane Landfill
City/State Louisville, Ky
Date: 5/5/03 Phone No.
Name of Citizen
Address

Do you live near the Site? If yes, how long? couple of blocks over in 1972

Are you familiar with EPA activities over the past years? familiar with some

What is your overall impression of the project? at first thought it was an inadequate job - they went in there in area & they would see some contamination surface to date. I think things could have been done better.

Overall, have you been pleased or displeased with cleanup actions at this Site? Overall displeased - felt nothing was done & not working. Felt that landfill should have been dug up and removed & truly "clean up" the area.

What effects, if any, have site operations had on the surrounding community? think there has been some little change in community. People were upset in the beginning - over time the landfill has been relocated. People still are behind an dumping area & with ATVs & Bikes taking over landfill.

Do you still have any concerns regarding EPA clean up activities of the Site? Don't know - don't have enough information to give a response.

Do you think you have been kept adequately informed about clean up activities at the Site? fairly well

Are you aware of any events, incidents, or activities at the site such as vandalism, trespassing, or emergency responses from local authorities? If so, please give details. currently a cutting grass trail/walk is being established along with a path is being built with plans to remove from sewerage residents negative impact on wildlife in area (down off ATVs & Bikes).

Is there someone else that you would like to recommend we contact for more information? Don't think of anyone.

Do you have any suggestions that EPA can implement to improve communication with the public? Direct mail & media & more internet.

Interview conducted by: Shirley Bennett
Date conducted: 5/5/2003

Environmental Consultants

2060 Reading Road
Suite 200
Cincinnati, Ohio 45202-1497

513 421-5353
Fax 513 421-2847
info@sci-engineers.com

SCS ENGINEERS

March 17, 2003
File No. 9000001.05

U.S. Army Corps of Engineers
CBLRL-ED-E
P.O. Box 59
Louisville, Kentucky 40201

Attention: Mr. John Jent

Subject: Condition of Landfill Gas Migration Control System
Lees Lane Landfill, Louisville, Kentucky

Gentlemen:

Thank you for contacting SCS Engineers last Friday, March 14, 2003, to discuss landfill gas related conditions at the Lees Lane Landfill. As you know, a landfill gas (LFG) migration control system was installed at this facility in about 1980. The system consists of approximately 30 vertical extraction wells, installed in the floodwall right-of-way, between the Lees Lane Landfill and the Riverside Gardens Subdivision located adjacent. The gas control system is located in virgin ground outside the refuse limits. Its purpose is to intercept landfill gas that might otherwise be available for migration toward homes located in Riverside Gardens.

When the system was first installed in 1980, landfill gas was found to have migrated up to 1,000 ft outward from the landfill, and into and among the homes of Riverside Gardens. This condition was particularly enhanced under conditions of rising flood waters in the Ohio River, and a rising water table. Under these conditions, landfill gas was apparently "squeezed out" to a smaller, subsurface unsaturated zone. Landfill gas was then found to be migrating to greater distances. An explosion in one of the residential furnaces within Riverside Gardens in about 1977 precipitated an investigation.

Collected landfill gases are of low methane content, and are free vented at a blower/vent facility also located within the floodwall right-of-way. SCS Engineers was the design engineer of record on this original system. I was personally involved at that time with management of the overall project. To date, SCS had performed three separate projects under contract to the Jefferson County Department of Public Works (DPW) at this facility. These included:

1. Investigation of landfill gas migration. This project was performed by SCS Engineers for the Jefferson County DPW beginning in 1978 and ending in 1979. Monitoring probes were installed within the Corps of Engineers floodwall between Lees Lane Landfill and Riverside Gardens. Subsequently, additional monitoring probes were installed throughout Riverside Gardens to determine the extent of landfill gas migration. The first phase of well installations within the floodwall right-of-way were later

Offices Nationwide

Form C-9
Correspondence with SCS
Engineers

"permanitized" and made part of the ongoing gas monitoring network. Monitoring of the probes out in Riverside Gardens itself was discontinued.

2. SCS was subsequently contracted to the Jefferson County DPW to design and oversee the installation of an LFG migration control system. This project began in 1979, and was completed in late 1980. Actual construction and operational start-up of the migration control system occurred during the summer of 1980. As referenced above, the gas migration control system consisted of approximately 30 extraction wells. Gas was collected in these wells by a blower located inside a blower/vent building. Vacuum was applied to individual wells. Gases were then withdrawn through a subsurface header, and directed back to the blower/vent building.

Immediately after start-up, the gas migration control system was found to be completely effective in mitigating the potential for laterally migrating gases. This was found to be the case both initially under normal conditions, and during subsequent flood stages of the Ohio River. In each case, the gas monitoring network described above was monitored, and readings were generally 0 percent methane, and always below the regulatory limit of 5 percent methane (a.k.a., the lower explosive limit or LEL).

3. SCS was then again contracted in 1985 and 1986. Our client was again the Jefferson County DPW. We were contracted to perform an investigation of the existing gas migration control system, to determine its effectiveness. At that point, the original system had been operational for about 5 years. SCS tested the condition of the entire migration control system, noted operating vacuums and gas compositions, and made recommendations on maintenance needed.

As I recall, our finding at the time was that about 25 percent of the efficiency of the system was gone. Specifically, about one quarter of the wells had broken or silted in, and were no longer effective in controlling laterally-migrating gas. Operating vacuum and flows had considerably diminished, also by at least 25 percent.

This degree of deterioration is typical for LFG migration control systems. Typically, the need for maintenance should be determined on at least an annual basis, and maintenance is likely required at 3-year cycles if the gas collection system is located within a settling and corrosive landfill environment. Alternatively, if the gas system is located in virgin ground (such as is the case here), maintenance at minimum 5-year cycles is likely required.

In our phone conversation the other day, you mentioned that the Metropolitan Sewer District (MSD) of Louisville has assumed ongoing monitoring of the gas monitoring probes, and apparently assumed that responsibility from the Jefferson County DPW at some juncture. Their monitoring has revealed that gas monitoring readings in those probes have been rising over time. A further deterioration of the gas migration control system is now suspected.

Mr. John Jent
March 17, 2003
Page 3

Apparently, the SCS investigation of 1985/1986 was the last observation on the operational effectiveness of the gas control system. If true, one could anticipate that significant deterioration (perhaps total failure) of the LFG collection system is likely at this point. If the system deteriorated 25 percent in the first five years, a much greater deterioration (perhaps to 100 percent) could be expected now. Of course, gas monitoring in the probes is reportedly still below LEL levels. If true, some effectiveness of the gas migration control system must be retained to this date.

In any event, we recommend that a thorough investigation of the operating efficiency of the LFG collection system be performed at the earliest date. The purpose of this program would be to observe operating conditions (well head vacuums, valve settings, physical conditions, and gas compositions). The total flow, vacuum/pressure and gas composition of the blower/vent should also be observed. Down-hole conditions at the extraction wells and any condensate traps should also be examined. The purpose here would be to determine whether wells and traps have physically failed, or silted in over time.

The outcome of this field investigation would be a report summarizing the condition of the system, and making recommendations for improvement. Those recommendations could call for total re-construction of the entire system, if substantial failure of the existing system has already occurred. In short, replacement of the system at that point may be a more productive economic application than attempting to rehabilitate the existing system.

The original work by SCS Engineers on this project was performed by James Walsh and other engineers at our Cincinnati, Ohio location. Most of those personnel remain with the firm. We would be quite interested in serving any client in an investigation of system conditions. We also stand available for maintenance, repair, and even replacement of the LFG system through our subsidiary organization, SCS Field Services. Field Services specializes in the maintenance, replacement, construction, and operation of LFG management systems.

Please contact the undersigned at any time for any further questions you may have, or if you wish to discuss specific work efforts. We appreciate your contacting SCS Engineers.

Sincerely,



James J. Walsh, P.E.
President
SCS ENGINEERS

JJW:rae